

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT
JUL 13 2017

RECEIVED

State of New Mexico **NM OIL CONSERVATION**
Energy Minerals and Natural Resources ARTESIA DISTRICT
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

JUL 13 2017 by appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1719937736 OPERATOR Initial Report Final Report

Name of Company WPX Energy Inc/RKI <i>246289</i>	Contact Karolina Blaney
Address 5315 Buena Vista Dr.	Telephone No. 970 589 0743
Facility Name: Federal Longview 12-15	Facility Type: Well Pad
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-41092	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	12	23S	28E	835	FNL	2010	FWL	Eddy

Latitude: 32.32508851N Longitude: -104.04285791W

NATURE OF RELEASE

Type of Release. Produced Water	Volume of Release: 25 Bbls	Volume Recovered: 25 Bbls
Source of Release Flowline	Date and Hour of Occurrence 6/29/2017	Date and Hour of Discovery 6/29/2017 - 7:00 hrs MT
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD Crystal Weaver & Michael Bratcher, BLM Shelly Tucker	
By Whom? Karolina Blaney	Date and Hour: 6/29/2017 - 14:40 hrs MT	<i>2:42pm</i>
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		

Describe Cause of Problem and Remedial Action Taken.*
The cause is equipment failure; corroded flowline. 25 bbls of produced water was spilled inside lined SPCC containment. All of the fluids were recovered. The containment liner was inspected immediately after the spill occurred. Based on the inspection, there is no evidence that the spilled fluids have left the containment.

Describe Area Affected and Cleanup Action Taken.*
The environment was not impacted by this spill. All fluids were contained inside lined SPCC containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Karolina Blaney</i>	OIL CONSERVATION DIVISION	
Printed Name: Karolina Blaney	Approved by Environmental Specialist: <i>Crystal Weaver</i>	
Title: Environmental Specialist	Approval Date: <i>7/17/17</i>	Expiration Date: <i>N/A</i>
E-mail Address: Karolina.blaney@wpenergy.com	Conditions of Approval: <i>FINAL</i>	Attached <input type="checkbox"/>
Date: 7/13/2017 Phone: 970-589-0743		

* Attach Additional Sheets If Necessary

Please refer to the New Mexico Oil Conservation Division Website for updated form(s) at:
<http://www.emnrd.state.nm.us/OCD/forms.html> Thank you

2RP-4296

7/19/17