

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.
NM 27919

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2.

7. If Unit of CA/Agreement, Name and/or No.

1. Type of Well

Oil Well Gas Well Other

8. Well Name and No.
Dewey "24" Fed 4

2. Name of Operator
Dinero Operating

9. API Well No.
4

3001542799

3a. Address
P.O. Box 10505
Midland, TX 79702

3b. Phone No. (include area code)

10. Field and Pool or Exploratory Area
Malaga - Delaware

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
1980 FNL 1980 FWL Sec. 24
24S, 28 E

11. Country or Parish, State
Eddy

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other _____
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

5-3-17 - Set 5 1/2 CIBP @ 2600'. Spot 25sx cmt on top of plug. Tag @ 2485'.

5-3-17 - Perf @ 1200'. Pumped & sqz 40sx. WOC Tag @ 1024'.

5-4-17 - Perf @ 600'. Pumped & sqz 145sx cmt to surf. Cut off Well Head. Top off w/20sx cmt. Installed dry hole marker. Job Complete.

Confirmed Tag w/BLM - Terry L.

Pressure test csg. good @ 500psi. 15-20 min.

Start Date: 5-1-17

Complete Date: 5-4-17

NM OIL CONSERVATION
ARTESIA DISTRICT

JUL 17 2017

RECEIVED

RECLAMATION
DUE 11-4-17

14. I hereby certify that the foregoing is true and correct.

Name (Printed/Typed)
Wayne Pinkerton

Title Owner

Signature

Wayne Pinkerton

Date 05/08/2017

Accepted for record
NMOC
R.L.B.

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

James C. Amos

Title

SPET

Date

7-11-17

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

CFO

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)