

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

JUL 17 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

DAB1720652142

OPERATOR

☒ Initial Report

☒ Final Report

Name of Company	Devon Energy Production Company	Contact	Wesley Ryan, Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No.	575-390-5436
Facility Name	State CW 2	Facility Type	Gas

Surface Owner State	Mineral Owner State	API No	30-015-33851
---------------------	---------------------	--------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	19	20S	28E	1500	North	1310	East	Eddy

Latitude: N 32.5621147 Longitude: W 104.2129745

NATURE OF RELEASE

Type of Release	Fire	Volume of Release	15 BBLS Oil & 32 BBLS PW	Volume Recovered	0 BBLS Oil & 0 BBLS PW
Source of Release	Oil tank	Date and Hour of Occurrence	7/03/2017 @ 4:35pm	Date and Hour of Discovery	7/03/2017 @ 4:35pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	OCD-Mike Bratcher		
By Whom?	Gilbert Sanchez, Asst. Foreman	Date and Hour	OCD- 7/3/16 @ 4:55pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	N/A		
If a Watercourse was Impacted, Describe Fully.* N/A					

Describe Cause of Problem and Remedial Action Taken.*

Lightning struck a 500 BBL fiberglass oil tank causing it to catch on fire. Upon arrival of the lease operator the well was immediately shut in and the fire was extinguished by the Carlsbad Fire Department.

Describe Area Affected and Cleanup Action Taken.*

Approximately 15 BBLS oil were burnt up inside the oil tank and 32 BBLS of produced water evaporated from the water tank sitting next to the oil tank due to the extreme heat of the fire. All fluids remained inside the tanks and none were released to the ground.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sarah Gallegos-Troublefield	OIL CONSERVATION DIVISION	
Printed Name: Sarah Gallegos-Troublefield	Approved by Environment NMOCD 7/17/17	
Title: Field Admin Support	Approval Date: 7/25/17	Expiration Date: N/A
E-mail Address: Sarah.Gallegos-Troublefield@dv.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 7/12/2017 Phone: 575.748.1864		

* Attach Additional Sheets If Necessary

2RP-4307