

**NM OIL CONSERVATION**  
ARTESIA DISTRICT

OCT 11 2017

Form C-141  
Revised August 8, 2011

District I  
1625 N. French Dr  
District II  
811 S. I  
District III  
1000 Ric  
District IV  
1220 S. S  
Please refer to the New Mexico Oil  
Conservation Division Website for  
updated form(s) at:  
[http://www.emnrd.state.nm.us/  
OCD/forms.html](http://www.emnrd.state.nm.us/OCD/forms.html)  
Thank you

State of New Mexico  
Minerals and Natural Resources  
Oil Conservation Division  
20 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED  
Submit to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**NAB1728558608** OPERATOR  Initial Report  Final Report

Name of Company	Chevron USA <b>4323</b>	Contact	Josepha DeLeon
Address	6301 Deauville Blvd, Midland, TX 79706	Telephone No.	575-263-0424
Facility Name:	HH SO 10 P3 8H	Facility Type:	Drilling Rig
Surface Owner	BLM	Mineral Owner:	BLM
		API No.	30-015-43937


**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	03	26S	27E	603	South	2066	West	Lea

Latitude: 32.0656613 Longitude: -104.180271

**NATURE OF RELEASE**

Type of Release: Spill	Volume of Release: 1.8 barrels diesel fuel	Volume Recovered: 0
Source of Release: 1" hose	Date and Hour of Occurrence 09/27/2017; 08:30 AM	Date and Hour of Discovery 09/27/2017; 08:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Crystal Weaver, Mike Bratcher - NMOCD Jim Amos, Shelly Tucker - BLM (notice was given due to unknown amount of diesel loss). C141 submitted as follow up only. Non-reportable release.	
By Whom? Josepha DeLeon	Date and Hour 09/28/2017; 07:50 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* Not Applicable		
Describe Cause of Problem and Remedial Action Taken.* Total of 1.8 barrels diesel fuel overflowed. 1.3 barrels of diesel was spilled off secondary containment onto caliche pad and .5 barrels seeped under containment.		
Describe Area Affected and Cleanup Action Taken.* 1" hose shut off and clean up of visible fluid was immediately started.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Josepha DeLeon	Approved by Environmental Specialist 	
Title: HES Compliance Support - Environmental	Approval Date: 10/12/17	Expiration Date: N/A
E-mail Address: jxd@chevron.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/> 2RP-4433
Date: 10/10/2017	Phone: 575-263-0424	

\* Attach Additional Sheets If Necessary