



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON
Governor
Betty Rivera
Cabinet Secretary

Lori Wrotenberg
Director
Oil Conservation Division

Completed

6-25-03

OK to release

217 South B Loco
7-303

Yates Petroleum Corporation
105 South 4th Street
Artesia, New Mexico 88210

Form C-103 Report of Plugging for your *Tallanage #1 SEC 32-T175-30E 30-015-04439*
Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

- ☒ 1. All pits have been filled and leveled.
- ☒ 2. Rat hole and cellar have been filled and leveled.
- ☒ 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- ☒ 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- ☒ 5. The dead men and tie downs have been cut and removed.
- ☒ 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.
- ☒ 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

[Signature]
Name

date
6-30-03

Van Barton
Field Rep. II

[Signature]
Title

2nd List

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-015-04439
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name:

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/> Plug & Abandon <input checked="" type="checkbox"/>	8. Well No. 1
2. Name of Operator Yates Petroleum Corporation	9. Pool name or Wildcat Queen-Grayburg-San Andres
3. Address of Operator 105 South Fourth Street - Artesia, NM 88210	
4. Well Location Unit Letter N : 990 feet from the South line and 1650 feet from the West line Section 32 Township 17S Range 30E NMPM Eddy County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>
OTHER: <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

5-29-2003 - Moved in and rigged up pulling unit and plugging equipment.
5-30-2003 - Nippled down wellhead and nipped up BOP. Dug out cellar. Rigged up floor and tubing equipment. Shut well in. NOTE: OCD had a problem with C-103.
5-31-6-2-2003 - RIH and tagged plug. Shut well in for night.
6-3-2003 - Circulated hole with plugging mud. Spotted 25 sacks Class C Neat cement from 2590-2440'. POOH with tubing. Rigged up wireline. RIH and perforated 7" casing at 1250'. POOH and rigged down wireline. RIH with cement retainer to 1169'. Squeezed with 60 sacks Class C Neat cement. Dumped 35' of cement on top of retainer. POOH with tubing. Shut well in for night.
6-4-2003 - Rigged up wireline. RIH and perforated 7" casing at 545'. POOH and rigged down wireline. RIH with cement retainer to 445'. Squeezed with 60 sacks Class C Neat cement. Dumped 35' of cement on top of retainer. POOH with tubing. Rigged down tubing equipment and floor. Nippled down BOP and casinghead. Installed 7" X 2" swedge with valve. Shut well in for night.

CONTINUED ON NEXT PAGE:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tina Huerta TITLE Reg. Compliance Supervisor DATE June 11, 2003

Type or print name Tina Huerta Telephone No. (505) 748-1471

(This space for State use)


APPROVED BY [Signature] TITLE Field Rep DATE JUL 3 2003

Conditions of approval, if any:

YATES PETROLEUM CORPORATION
Tallmadge #1
Section 32-T17S-R30E
Eddy County, New Mexico

SUNDRY NOTICE CONTINUED:

6-5-2003 - Rigged up wireline. RIH and perforated 7" & 8-5/8" casing at 100'. POOH and rigged down wireline. Installed 7" X 2" swedge with valve. Circulated 90 sacks Class C Neat cement down 7" and up to surface inside and outside of 8-5/8" casing. WOC. Cement stayed at surface. Cut off wellhead. Rigged down pulling unit and plugging equipment. Installed regulation abandonment marker. PLUGGED AND ABANDONED - FINAL REPORT. Plugging completed 6-4-2003.

_____

