

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTNM OIL CONSERVATION
ARTESIA DISTRICT
OCD Artesia

APR 03 2018

FORM APPROVED
OMB NO 1004-0137
Expires January 31, 2018**SUNDRY NOTICES AND REPORTS ON WELLS**
Do not use this form for proposals to drill or to re-enter an abandoned well Use form 3160-3 (APD) for such proposals5 Lease Serial No
NMNM99147

6 If Indian, Allottee or Tribe Name

7 If Unit or CA/Agreement, Name and/or No

SUBMIT IN TRIPLICATE - Other instructions on page 2

1 Type of Well

☒ Oil Well ☐ Gas Well ☐ Other8 Well Name and No
SLIDER 8 FEDERAL 2H

2 Name of Operator

DEVON ENERGY PRODUCTION COMPANY

Contact RONNIE SLACK
E-Mail ronnie.slack@dvn.com9 API Well No
30-015-38281-00-S1

3a Address

333 WEST SHERIDAN AVENUE
OKLAHOMA, OK 73102

3b Phone No (include area code)

Ph 405-552-4615

10 Field and Pool or Exploratory Area
WILLOW LAKE-BONE SPRING, SE

4 Location of Well (Footage Sec T R M or Survey Description)

Sec 8 T25S R29E NWSE 1690FSL 1385FEL

11 County or Parish, State

EDDY COUNTY, NM

12 CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☒ Notice of Intent☐ Subsequent Report☐ Final Abandonment Notice☐ Acidize☐ Alter Casing☐ Casing Repair☐ Change Plans☐ Convert to Injection☐ Deepen☐ Hydraulic Fracturing☐ New Construction☒ Plug and Abandon☐ Plug Back☐ Production (Start/Resume)☐ Reclamation☐ Recomplete☐ Temporarily Abandon☐ Water Disposal☐ Water Shut-Off☐ Well Integrity☐ Other

13 Describe Proposed or Completed Operation Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

1 MIRU P&A unit

2 POOH w/rod pump and 2-7/8" production tubing assembly from 6,806'

3 Set CIBP @ +/-7,000' Circulate wellbore w/10# salt gel mud

4 Spot 50 sx (500') CI C @ 7,000' - 6,500' Tag TOC

5 Spot 30 sx (300') CI C @ 5,610' - 5,310' Tag TOC (dv tool 5491')

6 Spot 30 sx (300') CI C @ 2,930' - 2,630' Tag TOC (9-5/8 shoe @ 2880')

7 Spot 30 sx (300') CI C @ 1,950' - 1,650' (T Bell Canyon @ 1939')

8 Perf @ 545' Pump 165 sx CI C in/out from 545' to surface

9 Cut wellhead off 3' below ground level Set dry hole marker

RECLAMATION PROCEDURE
ATTACHEDAccepted for record - NMOCD
4-4-18SEE ATTACHED FOR
CONDITIONS OF APPROVAL

14 I hereby certify that the foregoing is true and correct

Electronic Submission #399461 verified by the BLM Well Information System

For DEVON ENERGY PRODUCTION COM LP, sent to the Carlsbad

Committed to AFMSS for processing by PRISCILLA PEREZ on 01/04/2018 (18PP0659SE)

Name (Printed/Typed) RONNIE SLACK

Title PRODUCTION TECHNOLOGIST

Signature (Electronic Submission)

Date 01/03/2018

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By

James G. Jones

Title

Supv. PET

Date

3-20-18

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Carlsbad

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ****

DEVON ENERGY PRODUCTION COMPANY LP

Well Name SLIDER 8 FEDERAL 2H	Field WILLOW LAKE
Location 1690' FSL & 1385' FEL 08-25S-29E	County EDDY State NM
Elevation 2990' KB 2965' GL 25' KB to GL	Spud Date 12/15/10 Compl Date 5/16/11
API# 30-015-38281	Prepared by Ronnie Slack Date 1/3/18 Rev

CURRENT WELLBORE

BELL CANYON 1939
CHERRY CANYON 3813
BRUSHY CANYON 5117
BONE SPRING 6709'

17 1/2" Hole
13 3/8", 48#, H40, STC, @ 491'
Cmt'd w/550 sx to surface ✓

Rustler Surf
Castle 1320
B/Sa H 2870 +/-
Jel 2901

TOC 1,214 CBL

12-1/4" Hole
9-5/8", 40#, J55, LTC, @ 2,880
Cmt'd w/1300 sx to surf ✓

Bell 1939
Cherry 3813

Brushy 5117

DV Tool @ 5,491 ✓

Bone Spring 6707

201 Jts, 2 7/8", 6 5#, L80 prod tbg (8/23/13)

TAC @ 6,385

12 Jts, 2-7/8", 6 5#, L80 prod tbg (8/23/13)
SN @ 6,737

2 Jts, 2-7/8", 6 5#, L80 prod tbg (10/8/11)
Bull Plug @ 6 806'

Mixed rod string of 1"-(67 jts), 7/8"-(70 jts), 3/4"-(105 jts), 1"-(28 jts)

MD (ftKB)	Incl (°)	Azm (°)	TVD (ftKB)
2985	5	102	2980
4876	5	92	4864
6692	4	280	6675
6755	10	278	6738
6944	21	273	6920
7070	31	266	7033
7195	40	266	7134
7322	52	266	7223
7511	73	269	7313
7634	93	269	7329
8673	90	271	7280
9619	90	267	7277
11034	94	269	7228

8 3/4 hole
5-1/2", 17#, P110, @ 11,034
Cmt'd w/Stg 1 w/1385 sx
Cmt'd w/Stg 2 w/550 sx TOC @ 1214 CBL ✓

11,034 MD
7,228 TVD

Willow Lake, Bone Spring, SE
8,389' 11,022

FC @ 11,030

DEVON ENERGY PRODUCTION COMPANY LP

Well Name SLIDER 8 FEDERAL 2H		Field WILLOW LAKE	
Location 1690' FSL & 1385' FEL 08-25S-29E		County EDDY	State NM
Elevation 2990' KB 2965' GL 25' KB to GL		Spud Date 12/15/10	Compl Date 5/16/11
API# 30-015-38281	Prepared by Ronnie Slack	Date 1/3/18	Rev

PROPOSED PLUG & ABANDONMENT

BELL CANYON 1939
CHERRY CANYON 3813
BRUSHY CANYON 5117
BONE SPRING 6709

17 1/2" Hole
13 3/8", 48#, H40, STC, @ 491'
Cmt'd w/550 sx to surface

Proposed
3 Cut wellhead off 3 8GL Set dry hole marker
2 Pmp 165 sx C I C in/out from 545 to surface
1 Perf @ 545

TOC 1,214 CBL

Proposed
1 Spot 30 sx (300) C I C @ 1 950 1 650
(T Bell Canyon 1939)

12 1/4" Hole
9-5/8", 40#, J55, LTC, @ 2,880
Cmt'd w/1300 sx to surf

Proposed
1 Spot 30 sx (300) C I C @ 2 930 2 630 Tag

DV Tool @ 5,491

Proposed
1 Spot 30 sx (300) C I C @ 5 610 5,310 Tag

Proposed
2 Spot 50 sx (500) C I C @ 7 000 6 500 Tag
1 Set CIBP @ +/- 7 000 Circ w/10# salt gel mud

MD (ftKB)	Incl (°)	Azm (°)	TVD (ftKB)
2985	5	102	2980
4876	5	92	4864
6692	4	280	6675
6755	10	278	6738
6944	21	273	6920
7070	31	266	7033
7195	40	266	7134
7322	52	266	7223
7511	73	269	7313
7634	93	269	7329
8673	90	271	7280
9619	90	267	7277
11034	94	269	7228

8-3/4" hole
5-1/2", 17#, P110, @ 11,034
Cmt d w/Stg 1 w/1385 sx
Cmt d w/Stg 2 w/550 sx TOC @ 1214 CBL

11,034 MD
7,228 TVD

Willow Lake, Bone Spring, SE
8,389' 11,022

FC @ 11,030

**BUREAU OF LAND MANAGEMENT
Carlsbad Field Office
620 East Greene Street
Carlsbad, New Mexico 88220
575-234-5972**

**Permanent Abandonment of Federal Wells
Conditions of Approval**

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1

1 Plugging operations shall commence within **ninety (90)** days from the approval date of this Notice of Intent to Abandon

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2 **Notification** Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272, Eddy County, call 575-361-2822, Lea County, call 575-393-3612

3 **Blowout Preventers** A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet, a 3M system for a well not deeper than 13,636 feet, and a 5M system for a well not deeper than 22,727 feet.

4 **Mud Requirement** Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.

5 **Cement Requirement** Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. **Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.**

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs

6 Dry Hole Marker All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper) **The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off**

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached) The following information shall be permanently inscribed on the dry hole marker well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds)

7 Subsequent Plugging Reporting Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well **Show date well was plugged**

8 Trash All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill Burial on site is not permitted

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required See attached reclamation objectives



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office
620 E. Greene St.
Carlsbad, New Mexico 88220-6292
www.blm.gov/nm



In Reply Refer To 1310

Reclamation Objectives and Procedures

Reclamation Objective Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its pre-disturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- 1 The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2 For wells and/or access roads not having an approved plan or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3 The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4 Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation.

equipment to ensure that it meets BLM objectives Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation This will prompt a specialist to inspect the location to verify work was completed as per approved plans

- 5 The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished If the BLM objectives have not been met the operator will be notified and corrective actions may be required
- 6 It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection
- 7 At this time the BLM specialist will inspect the location and/or access road If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective

If there are any questions, please feel free to contact any of the following specialists

Jim Amos
Supervisory Petroleum Engineering Tech
575-234-5909, 575-361-2648 (Cell)

Arthur Arias
Environmental Protection Specialist
575-234-6230

Henryetta Price
Environmental Protection Specialist
575-234-5951

Shelly Tucker
Environmental Protection Specialist
575-234-5979

Trishia Bad Bear Hobbs Field Station
Natural Resource Specialist
575-393-3612