# RECEIVED

Form 3160-5 (February 2005)

OCD Artesia
IAPR 1 9 2018

FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007

	OINTIL	DOI	AILO	,
DEPA	RTMEN	T OF	THE	INTERIOR
DITTO	ATTOTT	CITEA	BEART	A OF MENT

BUREAU OF LAND MANAGEMENT II-ARTESIA O.C

5. Lease Serial No.

SUNDRY	NMNM82904					
Do not use th	nis form for proposals t ell. Use Form 3160-3 (	6. If Indian, Allottee or Tribe Name				
SUBMIT IN TR	IPLICATE- Other instr	7. If Unit or CA/Agreement, Name and/or No.				
	7 2707112 011701 11701			_		
1. Type of Well ☐ Gas Well ☐ Other				8. Well Name and No.		
2. Name of Operator EOG Resources, Inc.				Adeline ALN Fed 7		
EOG Resour	ces, Inc.	9. API Well No. 30-015-27248				
3a. Address PO Box 2267 Midland, TX 797	02	3b. Phone No. (inc	clude area code)	10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec.,	T., R., M., or Survey Description)	SAND DUNES DELAWARE				
Sec 6 T24S R31E SWNE 1980	FNL 1980FEL			11. County or Parish, State		
See of Tario Roll B Will 2 1900		Eddy County, New Mexico				
12. CHECK A	PPROPRIATE BOX(ES) TO	INDICATE NA	TURE OF NOTICE,	REPORT, OR OTHER DATA		
TYPE OF SUBMISSION			TYPE OF ACTION			
TIPE OF SUBINISSION				(Start/Resume) Water Shut-Off		
Notice of Intent	Acidize	Deepen				
	Alter Casing Casing Remain	Fracture Treat  New Constructi	Reclamation	Other		
Subsequent Report	Casing Repair Change Plans	Plug and Aband				
Final Abandonment Notice	Convert to Injection	Plug Back	Water Dispo			
6.spot 158x cmt from 930° 6.spot 155x cmt from 100° 5. Perf / Sc	25sx cmt @7712'-7465' !'-6644' !'-4945 0'-3854' SPOT/Pen =436' 4) 46 - 83	7-507	Run Co Solid f in/out and S Contact	R-III-P Solid plug Then Potash. Bl from 4200-Surf. Blag from 4146-830 of 51/2"CSG. Perf QZ depending on CBC et Jim Amos @ 575- 48 for Details after		
A .	Accepted for record .	NMOCD	TOC	Determined.		
Selow ground	level dry h	ole mas	Ker requir	red		
14. Thereby certify that the fore Name (Printed/Typed)	going is true and correct	1		SEE ATTACHED FOR		
Leslie Olivarez		Titl	le P&A Tech	COMPLETE FUR		
Signature Los l	ii klaz	Da	te 03/2	8 1 8 APPRO		
	THIS SPACE FOR	PEDERAL OF	R STATE OFFIC	CE USE		
Approved by  Conditions of approval, if any, are certify that the applicant holds lega which would entitle the applicant to Title 18 U.S.C. Section 1001 and Title States of Section 1001 and Title 18 U.S.C. Section 1001 and Title 18	or equitable title to those rights of conduct operations thereon.	in the subject lease	Office Carlo	Date 4-18-18  Lily to make to any department or agency of the United		
States any false, fictitious or fraudu	ent statements or representations	s as to any matter with	nin its jurisdiction.			

(Instructions on page 2)

RECLAMATION PROCEDURE ATTACHED

# Seog resources

### Well Equipment Report

#### ADELINE ALN FEDERAL #7

MD (RK	VERTICAL - Original Hole, 07/ (B) Vertical school	2/2014 9:00:00 AM ematic (actual)	3001527248	County	State New Mexico	SEC 6, TWP G, Eddy CO	245, RNG 31E,	UNIT KB-Gid (i
-276			Job Category Workover	Primary Job Type Equipment Failure	Department Production	10, Loay 00.,	Start Date 8/29/2014	End Date 9/2/2014
-138			Casing String			OD (in)	10 10 10 10 10 10 10 10 10 10 10 10 10 1	4 19 6 19 19
0	- P 1/1		Conductor Cas Casing Description	sing	/ 11	20	0.0	et Depth (fUKB) 40.
4			Surface Casing Casing Description	-	2 "	13 3/8	0.0	et Depth (fBKB) 557, et Depth (fIKB)
9			Intermediate C Casing Description		27/- 11	8 5/8	0.0	4,096.
13	ma cacuaritrovante en administrativado	AND THE PROPERTY OF THE PROPER	Production Cas Tubing String			5 1/2	0.0	8,170.
22			Tubing Description		Run Date	Set Depth (fix	B) Wellbore	Mary Control of State
31			Joints Rem Descri		(fl) OD (in) Grade	Wt (Ib/li)	Top (fiKB)   Bim (fik	B) Cum Length (fi
40		Conductor Casing; 20; 13.0; 40.0	Rod Strings Rod Description Tapered Rod S	tring	Run Date	ALIN STRANJANS	Set Depth (10	
44		111	Rod Compone	nts	and the second	8/29/2014	Malaka Kara	7,900.
49			1 Polishe	d Rod	30.00	(in) Grade 1 1/2 D (in) Grade	Top (fKB) Stm (f	25.0 7,905.0
53		Conductor Cement: 13.0	68 Sucker Joints   Hem Desc	Rod - Norris	1,700.00	1 D	Top (ft/S) Stm (f 25.0 1, Top (ft/S) Stm (f	725.0 7,875.0
221		fiKB; 53.0 fiKB	110 Sucker Joints Item Desc	tiplion	2,750.00	7/8 D		475.0 6,175.0
			125 Sucker Joints Item Desc	ription	3,125.00 Length (ft) OD	3/4 D (in) Grade		600.0 3,425.0
389			<b>Pumping Units</b>		300.00	1 D		900.0
557		13 3/8; 13.0; 557.0	API Designation C-640D-365-16 Current Stroke SP			Sheave Size (in:	Manufacturer Lufkin	Crank Type
561			Pumping Prime	7		Siblive Size fin	) Max Pitmar. Rod	Gear Box SN
586			Make Lufkin	Model NEMA D	Type SN Electric	Install (	Date Installed Cond	Removed
570		Surface Cement; 13.0 ftKB; 570.0 ftKB	RPM (rpm) # Bel	lis Belt Wode	Selt L	ength (in)	Belt X-sect	Sheave Size (in)
1,745	TO BELLEVILLE				/-		48-	
2,921		tubing; 2 7/8; 13.0; [8,002.00; 8,002.0			101/2a	1+ 8	580	
4,096		Intermediate Casing: 8 5/8;			21-	. / =	2056	
4.100		13.0; 4,096.0			TQ1/5a B 1 Sal	5	728	
4,105					Bell	e	150	
4,109		Intermediate Cement; 13.0 ftKB; 4,109.0 ftKB			cherry	,	/-	
5,327					cherry		(147	
6.544						-	.,,	
7,752	Ä				Brushy		684	
7.765	Perforated;				,			
7,767	ftKB				35	8	8509	
7,770								
7,790	Acid zing: 7,762.0-							
7,810	7.830.0			Pecf	7762	- 1090	02	
7,830						. 0		
7,887	Frac; 7,762.0- 8,002.0							
7.945		,						
8,002								
8,058			DVT	82	18			
B.114	ALCONO.	Production Cement: 13.0		86				
8,170		fiKB: 8,170.0 fiKB Production Casing: 5 1/2;						
8,305		13.0; 8.170.0						
6,442		To(?						
G Y Res	ources, Inc		Page	1/1			Report Printed	10/31/2017

SSF

#### BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

#### Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet, and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Below Ground Level Cap (Lesser Prairie-Chicken Habitat): All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged.</u>
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

<u>Timing Limitation Stipulation/Condition of Approval for Lesser Prairie-Chicken:</u>
From March 1<sup>st</sup> through June 15<sup>th</sup> annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted



## United States Department of the Interior

#### **BUREAU OF LAND MANAGEMENT**

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nin



In Reply Refer To: 1310

#### Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- 1. The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation

equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Henryetta Price Environmental Protection Specialist 575-234-5951

Shelly Tucker Environmental Protection Specialist 575-234-5979

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-39343612