

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
May 27, 2004

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO.

30-015-05714

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

E 6018

7. Lease Name or Unit Agreement Name

STATE

8. Well Number

3

9. OGRID Number

018862

10. Pool name or Wildcat

SHUGART

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  
PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

RAY WESTALL

3. Address of Operator

Box 4, Loco Hills NM 88255

4. Well Location

Unit Letter E : 1650 feet from the NORTH line and 1650 feet from the WEST line

Section 2 Township 19S Range 31E NMPM EDDY County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3626 GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type

Depth to Groundwater

Distance from nearest fresh water well

Distance from nearest surface water

Pit Liner Thickness:

mil

Below-Grade Tank: Volume

bbls;

Construction Material

RECEIVED

APR 17 2006

OCD-ARTESIA

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

P AND A ☐

CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

SET CIBP @ 3400' (TOP OF PERFS) CAP w/ 35' cmt

SPOT 300' cmt 2600 - 2300 (T/HATES TO B/SALT) TAG

\* SPOT 100' 100' - 200' (ACROSS 8 5/8" CSNG SHOE) TAG  
Perf + Sguz.

60' SURFACE PLUG

HEAVY MUD BETWEEN ALL PLUGS

\* Perf. + Sguz. @ 1020' (100' cmt pty. 1070' - 970') TAG.

Notify OCD 24 hrs. prior  
To any work done.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE

TITLE

DATE

Type or print name

E-mail address:

Telephone No. 627-2370

For State Use Only

APPROVED BY:

TITLE

DATE

Conditions of Approval (if any):

RAY WESTALL  
STATE #3  
30-015-05714

TOC SURFACE  
150' 8 5/8" 50 SXS

2340'  
B/SALT

2540'  
T/YATES

3410'  
T/QUEEN

2243' TOC

3433-69' PERFS

3692-3633' PERFS

4094-4106' PERFS

4217' 5 1/2" 300 SXS