Forth 3160-5 (June 2015)

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia


FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5. Lease Serial No. NMNM074936


SUNDRY N	OTICES AND REPORTS ON WELLS	
Do not use this	form for proposals to drill or to re-enter an	
handoned well	Hen form 2460 2 (ABD) for such proposals	

abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name				
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No. NMNM82041X				
1. Type of Well					8. Well Name and No. ETZ STATE UNIT 108				
Oil Well					9. API Well No.				
COG OPERATING LLC E-Mail: Abbym@bcmandassociates.com					30-015-04185-00-S1				
3a. Address 600 W ILLINOIS AVENUE MIDLAND, TX 79701  3b. Phone N. Ph: 432-56			. (include area code) 0-7161		10. Field and Pool or Exploratory Area GRAYBURG				
4. Location of Well (Footage, Sec., T.		11. Cour	11. County or Parish, State						
Sec 17 T17S R30E SENE Tract 2					EDDY COUNTY, NM				
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA									
TYPE OF SUBMISSION	ACTION								
Notice of Intent	☐ Acidize ☐		pen	☐ Production (Start/Resume)		☐ Water Shut-Off			
_	□ Alter Casing	☐ Hyd	raulic Fracturing	☐ Reclamation		■ Well Integrity			
☐ Subsequent Report ☐ Casing Repair		■ New Construction		☐ Recomplete		Other			
☐ Final Abandonment Notice	☐ Change Plans	🛛 Plug	and Abandon	□ Temporarily Abandon					
	Convert to Injection	☐ Plug	g Back	☐ Water Disposal	er Disposal				
following completion of the involved operations. If the operation results in a multiple completion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.  1. Tag 4?? CIBP @ 2860?. Spot 25 sx cmt @ 2860-2760?. 2710. Woc Tag.  2. Set 4?? CIBP @ 2860?. Circulate hole w/ MLF. Pressure test csg. Spot 25 sx cmt @ 2605-2305?. CTBP set @ 2483.  2. Set 4?? CIBP @ 2506?. Circulate hole w/ MLF. Pressure test csg. Spot 25 sx cmt @ 2505-2305?. CTBP set @ 2483.  3. Perf & Sqz 30 sx cmt 2020-4830?. WOC & Tag (8 5/8? Shoe) / 900  4. Spot 25 sx cmt @ 1100-1000?. WOC & Tag (B/Salt) / 060-960. Deep Accepted for Precord. NMOCD  Conditions of the involved and the operator has determined that the site is ready for final inspection. The precord is not sufficiently set of the precord. NMOCD  Conditions of the involved and the operator has determined that the site is ready for final inspection. The precord is not sufficiently set of the precord i									
14. I hereby certify that the foregoing is true and correct.  Electronic Submission #426520 verified by the BLM Well Information System  For COG OPERATING LLC, sent to the Carlsbad									
Committed to AFMSS for processing by DEBO			AH MCKINNEY on 07/06/2018 (18DLM0426SE)						
Name (Printed/Typed) ABIGAIL MONTGOMERY			Title AGENT	Title AGENT AUG 0.7 2018					
Signature (Electronic Submission)			Date 07/06/2018 DISTRICT II-ARTESIA O.C.D.						
THIS SPACE FOR FEDERAL OR STATE OFFICE USE									
Approved By  Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease			Title Serge	Title Sext. ALT Date					
which would entitle the applicant to condu	ct operations thereon.		Office Car	Asbed	1				
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.									

## **COG Operating LLC**



### COG Operating LLC



### BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

#### Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Below Ground Level Cap (Lesser Prairie-Chicken Habitat): All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

- 7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

<u>Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:</u>
From March 1<sup>st</sup> through June 15<sup>th</sup> annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted