

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTCarlsbad Field Office
OCD ArtesiaFORM APPROVED
OMB NO. 1004-0137
Date: January 31, 2018**SUNDRY NOTICES AND REPORTS ON WELLS**
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.*5. Lease Serial No.
MLC029419A

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 27. If Unit or CA/Agreement, Name and/or No.
892000276B

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other8. Well Name and No.
SKELLY UNIT 940

2. Name of Operator

CHEVRON USA INCORPORATED

Contact: SANDY BALLARD

E-Mail: sballard@concho.com

9. API Well No.
30-015-32599-00-S1

3a. Address

6301 DEAUVILLE BLVD
MIDLAND, TX 79706

3b. Phone No. (include area code)

Ph: 432-686-4373

10. Field and Pool or Exploratory Area
FREN Paddock

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 22 T17S R31E NWNW 990FNL 330FWL

11. County or Parish, State

EDDY COUNTY, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
☐ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off
☒ Subsequent Report	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamation	☐ Well Integrity
☐ Final Abandonment Notice	☐ Casing Repair	☐ New Construction	☐ Recomplete	☒ Other Venting and/or Flaring
	☐ Change Plans	☐ Plug and Abandon	☐ Temporarily Abandon	
	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

Skelly Unit 940

Skelly Unit 940 Battery

Permit approval: Electronic Submission # 411886

Actual gas flared for this battery for 4/20/2018 TO 7/19/2018 is as follows:

April

Total for Battery = 14462 MCF

May

Total for Battery = 1626 MCF

June

Total for Battery = 14726 MCF

Number of wells to flare: (63)

SKELLY UNIT 635 30-015-37657-00-S01

NM OIL CONSERVATION
ARTESIA DISTRICT

Accepted for record DEC 12 2018

RECEIVED

RECEIVED

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #446321 verified by the BLM Well Information System

For CHEVRON USA INCORPORATED, sent to the Carlsbad

Committed to AFMSS for processing by PRISCILLA PEREZ on 12/06/2018 (19PP0544SE)

Name (Printed/Typed) SANDY BALLARD

Title SENIOR ADMINISTRATIVE ASSISTANT

Signature

(Electronic Submission)

Date 12/04/2018

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

ACCEPTED FOR RECORD

Approved By

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

DEC 06 2018

/s/ Jonathon Shepard

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ****

Additional data for EC transaction #446321 that would not fit on the form

32. Additional remarks, continued

SKELLY UNIT 645 30-015-40727-00-
SKELLY UNIT 646 30-015-38362-00-
SKELLY UNIT 655 30-015-39145-00-
SKELLY UNIT 660 30-015-37245-00-
SKELLY UNIT 661 30-015-40092-00-
SKELLY UNIT 665 30-015-39347-00-
SKELLY UNIT 669 30-015-38348-00-
SKELLY UNIT 673 30-015-40093-00-
SKELLY UNIT 678 30-015-37474-00-
SKELLY UNIT 679 30-015-37820-00-
SKELLY UNIT 682 30-015-37477-00-
SKELLY UNIT 688 30-015-40102-00-
SKELLY UNIT 698 30-015-40103-00-
SKELLY UNIT 710 30-015-37969-00-
SKELLY UNIT 715 30-015-38346-00-
SKELLY UNIT 725 30-015-38378-00-
SKELLY UNIT 737 30-015-40095-00-
SKELLY UNIT 747 30-015-40096-00-
SKELLY UNIT 750 30-015-38284-00-
SKELLY UNIT 753 30-015-38252-00-
SKELLY UNIT 757 30-015-38363-00-
SKELLY UNIT 759 30-015-38672-00-
SKELLY UNIT 767 30-015-37476-00-
SKELLY UNIT 769 30-015-38361-00-
SKELLY UNIT 771 30-015-38104-00-
SKELLY UNIT 782 30-015-38015-00-
SKELLY UNIT 783 30-015-37885-00-
SKELLY UNIT 785 30-015-40097-00-
SKELLY UNIT 802 30-015-38347-00-
SKELLY UNIT 810 30-015-38450-00-
SKELLY UNIT 820 30-015-37886-00-
SKELLY UNIT 827 30-015-38350-00-
SKELLY UNIT 828 30-015-38443-00-
SKELLY UNIT 829 30-015-37983-00-
SKELLY UNIT 832 30-015-37984-00-
SKELLY UNIT 833 30-015-38448-00-
SKELLY UNIT 843 30-015-37985-00-
SKELLY UNIT 847 30-015-40729-00-
SKELLY UNIT 849 30-015-37517-00-
SKELLY UNIT 901 30-015-29326-00-0
SKELLY UNIT 935 30-015-31977-00-
SKELLY UNIT 939 30-015-32598-00-
SKELLY UNIT 940 30-015-32599-00-
SKELLY UNIT 943 30-015-32962-00-
SKELLY UNIT 944 30-015-32963-00-
SKELLY UNIT 945 30-015-32964-00-
SKELLY UNIT 946 30-015-32965-00-
SKELLY UNIT 947 30-015-32966-00-
SKELLY UNIT 948 30-015-32967-00-
SKELLY UNIT 949 30-015-32968-00-
SKELLY UNIT 958 30-015-34318-00-
SKELLY UNIT 959 30-015-34327-00-
SKELLY UNIT 961 30-015-34324-00-S1
SKELLY UNIT 962 30-015-34325-00-S1
SKELLY UNIT 963 30-015-34646-00-
SKELLY UNIT 964 30-015-34686-00-
SKELLY UNIT 976 30-015-38251-00-
SKELLY UNIT 978 30-015-36062-00-S01
SKELLY UNIT 979 30-015-38342-00-0
SKELLY UNIT 980 30-015-36063-00-S01
SKELLY UNIT 987 30-015-36497-00-
SKELLY UNIT 995 30-015-36473-00-S01

Reason for flare: UNPLANNED MIDSTREAM CURTAILMENT PLANT MAINTENANCE AND HLP