

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised May 08, 2003

WELL API NO.

30-015-26593

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

V-1576

7. Lease Name or Unit Agreement Name

East Burton Flat 36 State

8. Well Number

#1-S

9. OGRID Number

154903

10. Pool name or Wildcat

Undesignated Parkway Atoka

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☐ Other ☐

2. Name of Operator

St. Mary Land & Exploration Co.

3. Address of Operator

P.O. Box 7168

Billings MT 59103

4. Well Location

Unit Letter I : 2240 feet from the S line and 660 feet from the E line

Section 36 Township 19S Range 29E NMPM County Eddy

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3330' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☒

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Plug & Sidetrack ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

4/24 - 26/03 RUPU. POOH w/tbg. RU WL & set CIBP @ 10,600' and cap with 25' cement. Set another CIBP @ 8900' and cap with 25' cement. Lay down tbg and RD.

5/2 - 13/03 MI Patterson Rig #78 to pull csg and sidetrack. Jet cut 5½" csg at 8300' and POOH recovering casing. Spot 145 sx cement plug 7125-6700'. Dress plug to 6899' and attempt to kick off for sidetrack. Drill to 7005' without kicking off into formation. POOH. RIH and spot plug #2 with 300 sx cement from 7003-6350'. Drill out plug to 6515' and started to sidetrack. Getting 100% formation in returns at 6539'. Directionally drilling to target.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Herb R Thackeray TITLE Operations Engineer DATE 5/28/03

Type or print name Herb Thackeray Telephone No. 406-255-8627
(This space for State use)

APPROVED BY For record only B4 TITLE _____ DATE JUN 10 2003
Conditions of approval, if any: