Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OCD Artesia

FORM APPROVED OMB NO. 1004-0137

	Expires: January 31, 20
5.	Lease Serial No.
	NMNM82902

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

6. If Indian, Allottee or Tribe Name

SUBMIT IN 1		7. If Unit or CA/Agre	ement, Name and/or No.			
1. Type of Well Oil Well Gas Well Oth				8. Well Name and No. DOMINO AOJ FE		
2. Name of Operator EOG Y RESOURCES, INC	KAY MADDOX ox@eogresource	s.com		9. API Well No. 30-015-30121		
3a. Address PO BOX 2267 ATTENTION; MIDLAND, TX 79702	3b. Phone No. (Ph: 432-686-	nclude area code) 3658		10. Field and Pool or Exploratory Area HACKBERRY; WOLFCAMP		
4. Location of Well (Footage, Sec., T.	1)			11. County or Parish,	State	
Sec 9 T19S R31E Mer NMP N 32.672252 N Lat, 103.880836		-			EDDY COUNT	Y, NM
12. CHECK THE AF	PROPRIATE BOX(ES)	TO INDICAT	E NATURE O	F NOTICE, I	REPORT, OR OTI	HER DATA
TYPE OF SUBMISSION			TYPE OF	ACTION		
☐ Notice of Intent	☐ Acidize	□ Deepe	n	☐ Production	on (Start/Resume)	■ Water Shut-Off
_	□ Alter Casing	☐ Hydra	ulic Fracturing	☐ Reclamat	ion	■ Well Integrity
Subsequent Report	□ Casing Repair	☐ New (Construction	☐ Recomple	ete	Other
☐ Final Abandonment Notice	□ Change Plans	🛭 Plug a	nd Abandon	□ Tempora	rily Abandon	
	☐ Convert to Injection	🗖 Plug E	Back	□ Water Di	sposal	
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. EOG PLUGGED AND ABANDONED THIS WELL USING THE ATTACHED PROCEDURE RECEIVED JAN 1-7 2019 RECLAMATION PROCEDURE ATTACHED DISTRICT II-ARTESIA O.C.D. RECLAMATION PROCEDURE ATTACHED DUF_ 6-28-/9						
14. I hereby certify that the foregoing is Name (Printed/Typed) KAY MAD	448954 verified RESOURCES, IN 6 for processing	C,sent to the (by JAMES AMO	Carlsbad	19 ()	NTERED Ly 1-22-19	
Signature (Electronic S	1	Date 01/07/20	019			
Accepted for Resor		···-		OFFICE US	F	
VICENIE IV	THIS SPACE FO	OR FEDERAL	OR STATE	OFFICE US	<u> </u>	
Approved By James	THIS SPACE FO	OR FEDERAL	Title	VET		1-15-19 Date
	d. Approval of this notice does	s not warrant or	Title S			/-/5-/9 Date
Approved By Conditions of approval if any, are attache certify that the applicant holds legal or equ	d. Approval of this notice does itable title to those rights in the ct operations thereon. U.S.C. Section 1212, make it a	s not warrant or e subject lease	Title S Office #	VET O		

DOMINO AOJ FEDERAL #3 30-015-30121

L-09-19S-31E 1650 FSL & 660 FWL

WELL WAS PLUGGED AND ABANDONED

WELL WAS FLO	GGED AND ABANDONED
10/17/2018	MIRU
10/18/2018	SET CIBP @10,100' W/25 SXS CL H CMT, RDMO
11/18/2018	MIRU, TAG TOC @10,116', DRLD OUT CMT & CIBP
11/21/2018	RIG TAG OLD RBP @ 11,719', BLM APPRVD CHG IN PROCEDURE
	PMP 50 SXS CL H CMT
11/22/2018	TAG TOC @10,132', PMP 50 SXS CL H CMT
11/27/2018	TAG TOC @ 10,050', PMP 50 SXS CL H CMT
11/30/2018	TAG TOC @ 9907', DRLD OUT CMT, BLM SAID SET CIBP @ 10,100'
12/2/2018	SET CIBP @ 10,100' TAGGED CIBP @ 10,100'
12/4/2018	RIH, PMP 30 SXS CL H CMT
12/5/2018	TAG TOC @ 8540', WILL DO CMT
12/7/2018	RIH TAG TOC @ 8447', DO CMT, FELL THRU @ 8900', REVERSE HOLE CLEAN,
	TAG CIBP @ 10,061'
12/11/2018	RIH PMP 25.SXS CL C CMT
12/12/2018	TAG TOC @ 9848'
12/13/2018	PERF SQZ @ 6607' W/25 SXS CL C CMT, TAG TOC @ 6487', PMP 5 MORE SXS CMT
12/14/2018	PERF SQZ @ 4400', W/30 SXS CL C CMT
12/15/2018	TAG TOC @ 4330', PERF SQZ @ 4329', PMP 30 SXS CL C CMT, TAG TOC @ 4210',
	PERF SQZ @ 3465' W/25 SXS CL C CMT
12/18/2018	TAG TOC @ 3290', PERF SQZ @ 2245' W/40 SXS CL C CMT, TAG TOC @ 2080',
	PERF SQZ @ 1000' W/60 SXS CL C CMT
12/19/2018	TAG TOC @ 400', PERF SQZ @ 100' W/35 SXS CL C CMT, CIRC TO SURFACE,
	PMP ANOTHER 35 SXS CL C CMT, PER BLM DO LAST CMT PLUG
12/21/2018	DO TO 100', FELL THRU, CO TO 400' (HARD CEMENT)
12/22/2018	SET PKR @120', TST TO 300 PSI, HELD, SET PKR @ 70', TST TO 300 PSI- LOST PRESS
12/23/2018	RIH TO 150', PMP 150 SXS CL C CMT PRESS TEST TO 720 PSI – HELD
12/28/2018	RIH TAG TOC @ 18', PMP CMT TO SURFACE, VERIFIED CMT, RDMO



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of
 Operations must include adequate measures for stabilization and reclamation of disturbed lands.
 Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
 process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crystal Weaver Environmental Protection Specialist 575-234-5943

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612