Submit 1 Copy To Appropriate District State of New Mexico Office	Form C-103
District L _T (575) 393-6161 Energy, Minerals and Natural Resources 1625 N. Wench Dr., Hobbs, NM 88240	s Revised July 18, 2013 WELL API NO. 30-015-30919
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION	
District III – (505) 334-6178 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE X FEE
<u>District IV</u> – (505) 476-3460 Santa Fe, NM 8/505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	B-6846
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A. DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	State 20-B
1. Type of Well: Oil Well 🔀 Gas Well 🗌 Other	8. Well Number 2
2. Name of Operator Longfellow Energy, LP	9. OGRID Number 372210
3. Address of Operator 16803 Dallas Parkway	10. Pool name or Wildcat
Addison, TX, 75001	(28509)Grayburg Jackson 7RVS-QN-GB-SA
4. Well Location	
Unit Letter H : 2285 feet from the North line and 330 feet from the East line Section 20 Township 17S Range 29E NMPM County Eddy	
Section 20 Township 17S Range 29E NMPM County Eddy 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
3602 ' GR	,
12. Check Appropriate Box to Indicate Nature of Not	tice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK D PLUG AND ABANDON REMEDIAL	WORK 🕅 ALTERING CASING 🗌
TEMPORARILY ABANDON CHANGE PLANS COMMENCE	
OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent detail	s and give pertinent dates including actimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
1. Set CBP @ 2115'w/10' sand	
2. Perforate lower 7 Rivers 1132' - 1207'	RECEIVED
3. RIH w/ packer and tubing	
4. Stimulate 7 Rivers APR 0 4 2019	
5. Swab 7 Rivers	
6. POOH w/ packer 7. Run tubing pump and rods	
8. Start pumping well	
9. Produced 7 Rivers for 60 days.	
10. POOH w/ tbg & rods. Remove RBP. Run tubing and rods	s to commingle all zones.
Spud Date: Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my know	viedoe and helief
Thereby certify that the information above is true and complete to the best of my know	
SIGNATURE SIGNATURE Engineering Te	echnologist DATE 3/6/2019
Type or print name David Cain E-mail address:	fellowenergy.com PHONE: 972-590-9900
For State Use Only	
APPROVED BY Aren Charps TITLE Staff Mar DATE 4-18-19 Conditions of Approval (if any):	
Conditions of Approval (if any): Always list dates of work performed	
V V	

Ň.

٢.