



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON
Governor

Joanna Prukop
Cabinet Secretary
Acting Director
Oil Conservation Division

December 13, 2005

Marbob Energy Corp
PO Box 227
Artesia, NM 88211-0227

RECEIVED

APR 20 2006
OCD-ARTESIA

Form C-103 Report of Plugging for your Biscuit State #1 P-7-25s-30e API 30-015-33630 cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

- ☒ 1. All pits have been filled and leveled.
- ☒ 2. Rat hole and cellar have been filled and leveled.
- ☒ 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- ☒ 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- ☒ 5. The dead men and tie downs have been cut and removed.
- ☒ 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.
- ☒ 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

Name DIANA J. BRIGGS

Gerry Guye
Deputy Field Inspector

PRODUCTION ANALYST
Title

APRIL 13, 2006

Submit 3 Copies to Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-015-33630
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. VO-7066
7. Lease Name or Unit Agreement Name BISCUIT STATE
8. Well Number 1
9. OGRID Number 14049
10. Pool name or Wildcat CORRAL CANYON; DELAWARE

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

RECEIVED

2. Name of Operator
MARBOB ENERGY CORPORATION

DEC - 9 2005

3. Address of Operator
PO BOX 227, ARTESIA, NM 88211-0227

ARTESIA

4. Well Location
Unit Letter P : 330 feet from the SOUTH line and 330 feet from the EAST line
Section 7 Township 25S Range 30E NMPM County EDDY

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3179' GL

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water

Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

PLUGGED & ABANDONED AS FOLLOWS:

11/28/05 - SET CIBP @ 6400'. SPOT 25 SX CLASS "C" NEAT CMT ON TOP.
11/29/05 - SET CIBP @ 5100'. DUMP BAIL 35' CMT ON TOP. SET CIBP @ 3575'.
11/30/05 - CIRC WELL W/ MUD. SPOT 25 SX CLASS "C" NEAT CMT ON TOP OF CIBP.
CUT 5 1/2" CSG @ 2482'. POOH. LD.
12/1/05 - RIH TO 2550'. SPOT 40 SX CLASS "C" NEAT CMT.
12/2/05 - RIH TAGGED CMT @ 2393'. SPOT 80 SX CLASS "C" NEAT CMT @ 816'. WOC 4 HRS.
TAGGED CMT @ 662'. SPOT 20 SX CLASS "C" NEAT CMT FROM 60' TO SURFACE.
CUT OFF WELL HEAD. INSTALL DRY HOLE MARKER.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NM OGD guidelines ☐, a general permit ☐ or an (attached) alternative OGD-approved plan ☐.

SIGNATURE Diana Briggs TITLE PRODUCTION ANALYST DATE 12/9/05

Type or print name DIANA J. BRIGGS

E-mail address: PRODUCTION@MARBOB.COM Telephone No. (505) 748-3303

For State Use Only

APPROVED BY: [Signature] TITLE DATE MAY 05 2006

Conditions of Approval (if any):