

Submit 1 Copy To Appropriate District Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
**RECEIVED**  
Department of Energy and Natural Resources  
JAN 01 2020  
CONSERVATION DIVISION  
1220 South St. Francis Dr.  
SANTA FE, NM 87505  
**EMNRD-OGD-ARTESIA**

Form C-103  
Revised July 18, 2013

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-22001
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Premier Oil & Gas, Inc.		6. State Oil & Gas Lease No. KO 6527
3. Address of Operator PO Box 1246, Artesia, NM 88211-1246		7. Lease Name or Unit Agreement Name Eddy FV State
4. Well Location Unit Letter <u>K</u> : <u>1980</u> feet from the <u>South</u> line and <u>1980</u> feet from the <u>West</u> line Section <u>25</u> Township <u>20S</u> Range <u>27E</u> NMPM Eddy County		8. Well Number #2
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3317 GR		9. OGRID Number 017985
		10. Pool name or Wildcat Avalon; Delaware

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐  
CLOSED-LOOP SYSTEM ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐  
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Plug and Abandon Procedure:

- 1) RIH w/ tubing string and tag existing CIPB @ 2770'. Circulate well with plugging mud. Spot 35' cmt from 2770 - 2735'. POOH.
- 2) RIH w/ tubing string and CIBP. Set CIBP @ 2672'. Spot 35' of cmt from 2672 - 2637'. POOH.
- 3) Cut off wellhead and anchors. Cap well and install dry hole marker.

*Need Current & Proposed WBD*

Spud Date: 1/14/1977

Rig Release Date: N/A

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Vice President DATE 1/17/2020

Type or print name Daniel Jones E-mail address: dan.jones@premieroilgas.com PHONE: 972-470-0228

**For State Use Only**

APPROVED BY: [Signature] TITLE [Signature] DATE 1/23/20

Conditions of Approval (if any):

**DENIED**

**DENIED**

GC