Submit 3 Copies To Appropriate District Office	State of New M	Mexico	Form C-103
District I	rict I Energy, Minerals and Natural Resources		May 27, 2004
1625 N. French Dr., Hobbs, NM 88240		WELL API NO. 30-015-23793	
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION		5. Indicate Type of Lease	
District III 1220 South St. Francis Dr.		STATE FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505		•	
SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		Sharp QS	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		8. Well Number	
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other P&A	RECEIVED	1
2. Name of Operator			9. OGRID Number
Yates Petroleum Corpora	tion	OCT 0/3 2005	025575
3. Address of Operator 105 S. 4 th Street, Artesia,	NTM 00210	OCD-MATERIA	10. Pool name or Wildcat POW Strawn
	NW 88210	, • •	FOW Suawii
4. Well Location Unit Letter P: 660 feet from the South line and 660 feet from the East line			
Section 4 Township 17S Range 26E NMPM Eddy County 11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3356'GR			
Pit or Below-grade Tank Application or Closure			
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water			
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐			
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ PLUG AND ABANDON ☒			
PULL OR ALTER CASING			
OTHER:	П	OTHER:	п
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion.			
9/27/05 - Set a CIBP at 5328' with 35' cement on top.			
9/28/05 – Spotted 25 sx at 4327'-4087'. Perforated at 2355'. Spotted 25 sx at 2405'-2165'. Perforated at 1414'. Spotted 25 sx at 1464'. 9/29/05 – Tagged at 1064'. Perforated at 452'. Squeezed with 40 sx. WOC. Tagged at 300'. Perforated at 60'. Squeezed 20 sx to			
surface. Leave casing full. Cut off wellhead and anchors. Installed dry hole marker. WELL IS PLUGGED AND ABANDONED.			
FINAL REPORT.			
Approved as to plugging of the well bore. Liability under bond is retained until surface restoration,			
	under bond is retained until surface re	,	
environmental remediation and final inspection is completed.			
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.			
SIGNATURE TITLE Regulatory Compliance Supervisor DATE September 30, 2005			
THE Regulatory Compiliance Supervisor DATE September 30, 2005			
Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471			
For State Use Only			
APPROVED BY:	TITLE		DATE
Conditions of Approval (if any):			