Submit 3 Copies To Appropriate District Office	State of New Mexico			Form C-103	
District I	Energy, Minerals and Natural Resources		Revised June 10, 2003		
1625 N. French Dr., Hobbs, NM 88240 District II				WELL API NO. 30-015-10390	
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION			5. Indicate Type of Lease	
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		cis Dr.		FEE
District IV	Santa Fe, NM 87505		6. State Oil & G	1	
1220 S. St. Francis Dr., Santa Fe, NM 87505				E-9262	
Santa Fe, NM 87505				7. Lease Name or Unit Agreement Name North Benson Queen Unit	
1. Type of Well:		37	Eller Eller	8. Well Number	
Oil Well Gas Well	Other Injection	Well W	SCIVED CIA OF		10
2. Name of Operator	Minerals Limited Par	2 R	CENED 55	9. OGRID Num	ber
United Oil &	Minerals Limited Par	rthership OC)		5300
3. Address of Operator	1 To A 4* MM57	707	18 /	10. Pool name o	į (
4. Well Location	oank Dr., Austin, TX	78740-52	22.23.7.05	Que	en - Grayburg
4. Well Location					
Unit Letter <u>F</u> :	feet from	the <u>Nortl</u>	ı line and	_1650feet fro	m the <u>West</u> line
	an 1:	400 D	407		
Section 29 Township 18S Range 30E NMPM Eddy County 11. Elevation (Show whether DR, RKB, RT, GR, etc.)					
11. Elevation (Show whether DR, RKB, RI, GR, etc.) 3455 KB					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF IN				SEQUENT RE	
PERFORM REMEDIAL WORK	PLUG AND ABANDO	ON 🔲	REMEDIAL WOR	K □	ALTERING CASING 🗌
TEMPORARILY ABANDON	CHANGE PLANS	CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT			
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AND CEMENT JOB		
OTHER:			OTHER:		П
	leted operations (Clea			d give pertinent da	tes including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion					
or recompletion.					
7-11-03 Started in hole to tag CIBP @ 2714', tag up on salt ring @ 651'. 7-14-03 Washed doen to 2664', circ. hole w/mud, spot 25 sx @2664'. 7-15-03 Run stretch on csg. showed 500', perf @ 1305' & sqz 65 sx. Tagged cmt @ 1118'. 7-16-03 Cut csg @ 535', lay down 5-1/2" csg. Spot 65 sx 600-300'. WOC 3 hrs & tagged cmt @ 346'. Spot 100 sx plug to surface. POOH w/tbg. Spot 5 sx to cap well off. Cut off wellhead, install dry hole marker & clean location. RDMO.					
I hereby certify that the information		lete to the be	st of my knowledg	e and belief.	
SIGNATURE Many Curlis	statton	TITLE_R	egulatory Coordin	ator	DATE <u>7/30/2003</u>
Type or print name Mary Curl	iss Patton	E-mail addre	ss: <u>mpatton@uo</u>	minc.com Tele	phone No. (512) 328-8184
(This space for State use)					
APPPROVED BYConditions of approval, if any	MAROCE	TITLE			DATE
Conditions of approval, if and	,	_ IIILE			DAIL
Accepted					