Office Option 10 Appropriate District	State of 3	New Mexico	Form C-103	•
District I	Energy, Minerals	and Natural Resources	May 27, 2004	<u>.</u>
1625 N. French Dr., Hobbs, NM 88240			WELL API NO. 30-015-22562	1
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERV	ATION DIVISION	5. Indicate Type of Lease	-{
District III	1220 South	St. Francis Dr.	STATE TEE	İ
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe	, NM 87505	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505		• •	E-952	
	TICES AND REPORTS ON	WELLS	7. Lease Name or Unit Agreement Name	7
(DO NOT USE THIS FORM FOR PROP	OSALS TO DRILL OR TO DEE!	EN OR PLUG BACK TO A		
DIFFERENT RESERVOIR. USE "APPL PROPOSALS.)	ICATION FOR PERMIT" (FOR!	M C-101) FOR SUCH	Eddy GZ State Com	
1. Type of Well: Oil Well	Gas Well Other	RECEIVED	8. Well Number	1
2. Name of Operator		- HEULIVER	9. OGRID Number	7
Harvard Petroleum Co	rporation	NOV 1 7 2005		_
3. Address of Operator		OOD:AATESIA	10. Pool name or Wildcat	
PO Box 936 Roswell,	NM 88201	AAA HAII MAHA	W. Millman, Grayburg	_
4. Well Location	1000		CCO A A Broke	
	: 1980 feet from the		660 feet from the East line	
Section 12	Township 10		NMPM Eddy County	
		ether DR, RKB, RT, GR, etc.,		
Pit or Below-grade Tank Application	3489.1 G	-K		7
Pit typeDepth to Ground		rest fresh water well Dist	ance from scarest surface water	1
			estruction Material	
				لــ
12. Check	Appropriate Box to In	dicate Nature of Notice,	Report or Other Data	
NOTICE OF I	NTENTION TO:	SUB	SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK			· · ·	
TEMPORARILY ABANDON	CHANGE PLANS	☐ COMMENCE DR	LLING OPNS. PAND A	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	TJOB []	
OTUCD:		C) OTHER	п	
OTHER:	inleted operations (Clearly	OTHER:	d give pertinent dates, including estimated dat	_ lc
13. Describe proposed or com	upleted operations. (Clearly work). SEE RULE 1103. F	state all pertinent details, an	d give pertinent dates, including estimated datatach wellbore diagram of proposed completio	te on
13. Describe proposed or com	upleted operations. (Clearly work). SEE RULE 1103. F	state all pertinent details, an	d give pertinent dates, including estimated datatach wellbore diagram of proposed completion	_ te on
13. Describe proposed or come of starting any proposed was or recompletion.	vork). SEE RULE 1103. F	state all pertinent details, and or Multiple Completions: At	tach wellbore diagram of proposed completio	_ tc on
13. Describe proposed or come of starting any proposed was or recompletion. 1. 4/7/05 Tbg. 1800',	work). SEE RULE 1103. F	v state all pertinent details, and or Multiple Completions: At w/ 2% CaCl, NOC &	tach wellbore diagram of proposed completio tag @ 1855'.	_ te on
13. Describe proposed or composed or composed or completion. 1. 4/7/05 Tbg. 1800', 2. 4/7/05 Tbg. 1800',	spot 40 sx. cmt.	w/ 2% CaCl, WOC & WOC & tag next da	tach wellbore diagram of proposed completio tag @ 1855'.	_ te on
13. Describe proposed or composed or composed or recompletion. 1. 4/7/05 Tbg. 1800', 2. 4/7/05 Tbg. 1800', 3. 4/8/05 Tbg. 1676',	spot 40 sx. cmt. spot 30 sx. cmt. circulate hole w	w/ 2% CaCl, WOC & WOC & tag next day	tach wellbore diagram of proposed completio tag @ 1855'.	_ te on
13. Describe proposed or composed or composed or completion. 1. 4/7/05 Tbg. 1800', 2. 4/7/05 Tbg. 1800', 3. 4/8/05 Tbg. 1676', 4. 4/8/05 Tbg. 527', or	spot 40 sx. cmt. spot 30 sx. cmt., circulate hole waterculate 190 sx.	w/ 2% CaCl, WOC & WOC & tag next day	tach wellbore diagram of proposed completio tag @ 1855'.	- te on
13. Describe proposed or come of starting any proposed was or recompletion. 1. 4/7/05 Tbg. 1800', 2. 4/7/05 Tbg. 1800', 3. 4/8/05 Tbg. 1676', 4. 4/8/05 Tbg. 527', 5. 4/8/05 POOH tbg., fi	spot 40 sx. cmt. spot 30 sx. cmt., circulate hole watericulate 190 sx.	w/ 2% CaCl, WOC & WOC & tag next day MLF. cmt. to surface.	tach wellbore diagram of proposed completion tag @ 1855'. ay @ 1676'.	on
13. Describe proposed or come of starting any proposed was or recompletion. 1. 4/7/05 Tbg. 1800', 2. 4/7/05 Tbg. 1800', 3. 4/8/05 Tbg. 1676', 4. 4/8/05 Tbg. 527', 5. 4/8/05 POOH tbg., fi	spot 40 sx. cmt. spot 30 sx. cmt., circulate hole watericulate 190 sx.	w/ 2% CaCl, WOC & WOC & tag next day MLF. cmt. to surface.	tach wellbore diagram of proposed completio tag @ 1855'.	on
13. Describe proposed or come of starting any proposed was or recompletion. 1. 4/7/05 Tbg. 1800', 2. 4/7/05 Tbg. 1800', 3. 4/8/05 Tbg. 1676', 4. 4/8/05 Tbg. 527', 675, 5. 4/8/05 POOH tbg., fi	spot 40 sx. cmt. spot 30 sx. cmt., circulate hole watericulate 190 sx.	w/ 2% CaCl, WOC & WOC & tag next day MLF. cmt. to surface.	tach wellbore diagram of proposed completion tag @ 1855'. ay @ 1676'.	on
13. Describe proposed or come of starting any proposed was or recompletion. 1. 4/7/05 Tbg. 1800', 2. 4/7/05 Tbg. 1800', 3. 4/8/05 Tbg. 1676', 4. 4/8/05 Tbg. 527', 675, 5. 4/8/05 POOH tbg., fi	spot 40 sx. cmt. spot 30 sx. cmt., circulate hole watericulate 190 sx.	w/ 2% CaCl, WOC & WOC & tag next day MLF. cmt. to surface.	tach wellbore diagram of proposed completion tag @ 1855'. ay @ 1676'.	on
13. Describe proposed or come of starting any proposed was or recompletion. 1. 4/7/05 Tbg. 1800', 2. 4/7/05 Tbg. 1800', 3. 4/8/05 Tbg. 1676', 4. 4/8/05 Tbg. 527', 5. 4/8/05 POOH tbg., fi	spot 40 sx. cmt. spot 30 sx. cmt. circulate hole waterculate 190 sx. cirl well bore. If wellhead & ancher	w/ 2% CaCl, WOC & WOC & tag next day MLF. cmt. to surface.	tach wellbore diagram of proposed completion tag @ 1855'. ay @ 1676'.	on
13. Describe proposed or come of starting any proposed was or recompletion. 1. 4/7/05 Tbg. 1800', 2. 4/7/05 Tbg. 1800', 3. 4/8/05 Tbg. 1676', 4. 4/8/05 Tbg. 527', 5. 4/8/05 POOH tbg., fi	spot 40 sx. cmt. spot 30 sx. cmt., circulate hole waterculate 190 sx. fill well bore. Standard & anche Approved as to pluggi	w/ 2% CaCl, WOC & WOC & tag next day MLF. cmt. to surface.	tach wellbore diagram of proposed completion tag @ 1855'. ay @ 1676'.	on
13. Describe proposed or come of starting any proposed was or recompletion. 1. 4/7/05 Tbg. 1800', 2. 4/7/05 Tbg. 1800', 3. 4/8/05 Tbg. 1676', 4. 4/8/05 Tbg. 527', 5. 4/8/05 POOH tbg., fi	spot 40 sx. cmt. spot 30 sx. cmt., circulate hole was circulate 190 sx. cill well bore. If wellhead & anche Approved as to pluggi under bond is retained environmental remedia.	w/ 2% CaCl, WOC & WOC & tag next day MLF. cmt. to surface.	tach wellbore diagram of proposed completion tag @ 1855'. ay @ 1676'.	on
13. Describe proposed or come of starting any proposed was or recompletion. 1. 4/7/05 Tbg. 1800', 2. 4/7/05 Tbg. 1800', 3. 4/8/05 Tbg. 1676', 4. 4/8/05 Tbg. 527', 5. 4/8/05 POOH tbg., fi	spot 40 sx. cmt. spot 30 sx. cmt., circulate hole was circulate 190 sx. fill well bore. If wellhead & anche Approved as to pluggiounder bond is retained	w/ 2% CaCl, WOC & WOC & tag next day MLF. cmt. to surface. nors, install dry hang of the well bore. Liability until surface restoration,	tach wellbore diagram of proposed completion tag @ 1855'. ay @ 1676'.	on
13. Describe proposed or come of starting any proposed was or recompletion. 1. 4/7/05 Tbg. 1800', 2. 4/7/05 Tbg. 1800', 3. 4/8/05 Tbg. 1676', 4. 4/8/05 Tbg. 527', 5. 4/8/05 POOH tbg., fi	spot 40 sx. cmt. spot 30 sx. cmt., circulate hole was circulate 190 sx. cill well bore. If wellhead & anche Approved as to pluggi under bond is retained environmental remedia.	w/ 2% CaCl, WOC & WOC & tag next day MLF. cmt. to surface. nors, install dry hang of the well bore. Liability until surface restoration,	tach wellbore diagram of proposed completion tag @ 1855'. ay @ 1676'.	on
13. Describe proposed or come of starting any proposed was or recompletion. 1. 4/7/05 Tbg. 1800', 2. 4/7/05 Tbg. 1800', 3. 4/8/05 Tbg. 1676', 4. 4/8/05 Tbg. 527', 5. 4/8/05 POOH tbg., fi	spot 40 sx. cmt. spot 30 sx. cmt., circulate hole was circulate 190 sx. cill well bore. If wellhead & anche Approved as to pluggi under bond is retained environmental remedia.	w/ 2% CaCl, WOC & WOC & tag next day MLF. cmt. to surface. nors, install dry hang of the well bore. Liability until surface restoration,	tach wellbore diagram of proposed completion tag @ 1855'. ay @ 1676'.	on
13. Describe proposed or compostarting any proposed or or recompletion. 1. 4/7/05 Tbg. 1800', 2. 4/7/05 Tbg. 1800', 3. 4/8/05 Tbg. 1676', 4. 4/8/05 Tbg. 527', 5. 4/8/05 POOH tbg., fi 6. 4/8/05 RDMO. Cut of	spot 40 sx. cmt. spot 30 sx. cmt., circulate hole w/circulate 190 sx. fill well bore. Approved as to pluggi under bond is retained environmental remedia completed.	w/ 2% CaCl, WOC & WOC & tag next day MLF. cmt. to surface. nors, install dry lang of the well bore. Liability until surface restoration, atton and final inspection is	tach wellbore diagram of proposed completion tag @ 1855'. ay @ 1676'. nole marker, and clean location to the second completion tag in the second completion tag	ion.
13. Describe proposed or compostarting any proposed or or recompletion. 1. 4/7/05 Tbg. 1800', 2. 4/7/05 Tbg. 1800', 3. 4/8/05 Tbg. 1676', 4. 4/8/05 Tbg. 527', 5. 4/8/05 POOH tbg., fi 6. 4/8/05 RDMO. Cut of	spot 40 sx. cmt. spot 30 sx. cmt., circulate hole w/circulate 190 sx. fill well bore. Approved as to pluggi under bond is retained environmental remedia completed.	w/ 2% CaCl, WOC & WOC & tag next day MLF. cmt. to surface. nors, install dry lang of the well bore. Liability until surface restoration, atton and final inspection is	tag @ 1855'. ay @ 1676'. nole marker, and clean locati	ion.
13. Describe proposed or composed or composed or recompletion. 1. 4/7/05 Tbg. 1800', 2. 4/7/05 Tbg. 1800', 3. 4/8/05 Tbg. 1676', 4. 4/8/05 Tbg. 527', 5. 4/8/05 POOH tbg., fi 6. 4/8/05 RDMO. Cut of	spot 40 sx. cmt. spot 30 sx. cmt., circulate hole w/circulate 190 sx. fill well bore. Approved as to pluggi under bond is retained environmental remedia completed.	w/ 2% CaCl, WOC & WOC & tag next day MLF. cmt. to surface. nors, install dry lang of the well bore. Liability until surface restoration, ation and final inspection is	tag @ 1855'. ay @ 1676'. nole marker, and clean location of the state of the stat	ion.
13. Describe proposed or compostarting any proposed or or recompletion. 1. 4/7/05 Tbg. 1800', 2. 4/7/05 Tbg. 1800', 3. 4/8/05 Tbg. 1676', 4. 4/8/05 Tbg. 527', 5. 4/8/05 POOH tbg., ff 6. 4/8/05 RDMO. Cut of	spot 40 sx. cmt. spot 30 sx. cmt. circulate hole waterculate 190 sx. fill well bore. f wellhead & anch Approved as to plugging under bond is retained environmental remediate completed. The above is true and completed to the complete or closed according to NMOCD	w/ 2% CaCl, WOC & WOC & tag next day MLF. cmt. to surface. nors, install dry lang of the well bore. Liability until surface restoration, ation and final inspection is te to the best of my knowledge guideliaes , a general permit	tach wellbore diagram of proposed completion tag @ 1855'. ay @ 1676'. nole marker, and clean location to the second completion tag in the second completion tag	ion.
13. Describe proposed or composed or composed or recompletion. 1. 4/7/05 Tbg. 1800', 2. 4/7/05 Tbg. 1800', 3. 4/8/05 Tbg. 1676', 4. 4/8/05 Tbg. 527', 5. 4/8/05 POOH tbg., fi 6. 4/8/05 RDMO. Cut of	spot 40 sx. cmt. spot 30 sx. cmt. circulate hole waterculate 190 sx. fill well bore. f wellhead & anch Approved as to plugging under bond is retained environmental remediate completed. The above is true and completed to the complete or closed according to NMOCD	w/ 2% CaCl, WOC & WOC & tag next day MLF. cmt. to surface. nors, install dry leading of the well bore. Liability until surface restoration, ation and final inspection is te to the best of my knowledgeddeliaes , a general permit. TITLE Agent B-mail address:	tag @ 1855'. ay @ 1676'. nole marker, and clean location of the second completion of the second completion of the second completion of the second complete control of the second complete co	ion.
13. Describe proposed or compostarting any proposed or or recompletion. 1. 4/7/05 Tbg. 1800', 2. 4/7/05 Tbg. 1800', 3. 4/8/05 Tbg. 1676', 4. 4/8/05 Tbg. 527', 5. 4/8/05 POOH tbg., ff 6. 4/8/05 RDMO. Cut of	spot 40 sx. cmt. spot 30 sx. cmt. circulate hole waterculate 190 sx. fill well bore. f wellhead & anch Approved as to plugging under bond is retained environmental remediate completed. The above is true and completed to the complete or closed according to NMOCD	w/ 2% CaCl, WOC & WOC & tag next day MLF. cmt. to surface. nors, install dry leading of the well bore. Liability until surface restoration, ation and final inspection is te to the best of my knowledgeddeliaes , a general permit. TITLE Agent B-mail address:	tag @ 1855'. ay @ 1676'. nole marker, and clean location of the second completion of the second completion of the second completion of the second complete control of the second complete co	ion.
13. Describe proposed or composed or completion. 1. 4/7/05 Tbg. 1800', 2. 4/7/05 Tbg. 1800', 3. 4/8/05 Tbg. 1676', 4. 4/8/05 Tbg. 527', 5. 4/8/05 POOH tbg., ff 6. 4/8/05 RDMO. Cut of Thereby certify that the information grade tank has been/will be constructed. SIGNATURE Type or print name Roger Market State Use Only	spot 40 sx. cmt. spot 30 sx. cmt. circulate hole waterculate 190 sx. fill well bore. f wellhead & anch Approved as to plugging under bond is retained environmental remediate completed. The above is true and completed to the complete or closed according to NMOCD	w/ 2% CaCl, WOC & WOC & tag next day MLF. cmt. to surface. nors, install dry hang of the well bore. Liability until surface restoration, ation and final inspection is te to the best of my knowledgeddelines [], a general permit [] TITLE Agent E-mail address:	tag @ 1855'. ay @ 1676'. nole marker, and clean location of the control of the	ion.
13. Describe proposed or composed or completion. 1. 4/7/05 Tbg. 1800', 2. 4/7/05 Tbg. 1800', 3. 4/8/05 Tbg. 1676', 4. 4/8/05 Tbg. 527', 5. 4/8/05 POOH tbg., ff 6. 4/8/05 RDMO. Cut of I hereby certify that the information grade tank has been/will be constructed. SIGNATURE Type or print name Roger Market Use Only APPROVED BY:	spot 40 sx. cmt. spot 30 sx. cmt. circulate hole waterculate 190 sx. fill well bore. f wellhead & anch Approved as to plugging under bond is retained environmental remediate completed. The above is true and completed to the complete or closed according to NMOCD	w/ 2% CaCl, WOC & WOC & tag next day MLF. cmt. to surface. nors, install dry leading of the well bore. Liability until surface restoration, ation and final inspection is te to the best of my knowledgeddeliaes , a general permit. TITLE Agent B-mail address:	tag @ 1855'. ay @ 1676'. nole marker, and clean location of the control of the	ion.
13. Describe proposed or composed or completion. 1. 4/7/05 Tbg. 1800', 2. 4/7/05 Tbg. 1800', 3. 4/8/05 Tbg. 1676', 4. 4/8/05 Tbg. 527', 5. 4/8/05 POOH tbg., ff 6. 4/8/05 RDMO. Cut of Thereby certify that the information grade tank has been/will be constructed. SIGNATURE Type or print name Roger Market State Use Only	spot 40 sx. cmt. spot 30 sx. cmt. circulate hole waterculate 190 sx. fill well bore. f wellhead & anch Approved as to plugging under bond is retained environmental remediate completed. The above is true and completed to the complete or closed according to NMOCD	w/ 2% CaCl, WOC & WOC & tag next day MLF. cmt. to surface. nors, install dry hang of the well bore. Liability until surface restoration, ation and final inspection is te to the best of my knowledgeddelines [], a general permit [] TITLE Agent E-mail address:	tag @ 1855'. ay @ 1676'. nole marker, and clean location of the control of the	ion.