

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87412  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources  
OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

WELL API NO.  
30-005-63550

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.  
VA-2034

7. Lease Name or Unit Agreement Name:

Gasby BCD State Com

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☒ Other ☐

2. Name of Operator

Yates Petroleum Corporation

3. Address of Operator

105 S. 4<sup>th</sup> Street Artesia, NM 88210

8. Well No.

1

9. Pool name or Wildcat

Wildcat Precambrian

4. Well Location

Unit Letter D : 660 feet from the North line and 660 feet from the West line

Section 20 Township 10S Range 27E NMPM Chaves County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

3788'GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

REMEDIAL WORK ☐

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETION ☐

CASING TEST AND CEMENT JOB ☐

OTHER:

☐

OTHER: Perforate and stimulate

☒

Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

7/21/03 - TOC 4047' CBL. Perforate Strawn 6312'-6330' (72).

7/22/03 - Acidize Strawn with 950g 7-1/2% IC acid and 108 balls.

7/23/03 - Set CIBP at 6300' and cap with 35' cement. Perforate Wolfcamp 5834'-5844' (40).

7/24/03 - Acidize Wolfcamp 5834'-5844' with 1000g 15% IC HCL acid with 60 ball sealers.

7/28/03 - Re-acidize with 7000g 15% IC HCL acid and 40 balls.

8/1-3/03 - Perforate Wolfcamp 5478'-5496' (38).

8/4/03 - Acidize Wolfcamp 5478'-5496' with 1850g 20% IC acid and 60 balls. Set ASI 10K packer with 2.25" on/off tool at 5413'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tina L. Huerta TITLE Regulatory Compliance Supervisor DATE August 8, 2003

Type or print name Tina L. Huerta

Telephone No. 505-748-1471

(This space for State use)

APPROVED BY FOR RECORDS ONLY TITLE DATE

Conditions of approval, if any:

AUG 15 2003