Submit 3 Copies 10 Appropriate District State of New Mexico	Form C-103
District I Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION INVISION	30-015-34545
District III 1220 South St. Francis Or 3	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NN 87410	STATE FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.
1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 Santa Fe, NM 27 27 27 27 27 28 28 28 29 20 20 20 20 20 20 20 20 20 20 20 20 20	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEPRESSOR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C. 1917) FOR 3 (C. 1917)	Dunaway 23
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other	8. Well Number
1. Type of well. On well Gas well Goulet	1
2. Name of Operator	9. OGRID Number
Devon Energy Production Company, LP	6137
3. Address of Operator	10. Pool name or Wildcat
20 North Broadway Oklahoma City, Oklahoma 73102-8260 (405) 552-7802	Otis; Morrow (Gas)
4. Well Location	
Unit Letter_B_:1000feet from thenorth line and1510feet from theeast line	
Section 23 Township 22S Range 27E NMPM Eddy County, NM 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
11. Elevation (Snow whether DR, RKB, RI, GR, etc.) 3077'	
Pit or Below-grade Tank Application or Closure	
Pit type Depth to Groundwater Distance from nearest fresh water well Dist	ance from nearest surface water
	nstruction Material
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
	SECULEINI REPURT OF
	·
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORLD COMMENCE DRI	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORL TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT	C ☐ ALTERING CASING ☐ LLING OPNS.☐ P AND A ☐ F JOB ☐
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORL TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT OTHER: Drillin	ALTERING CASING LLING OPNS. P AND A JOB G Operations
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT OTHER: OTHER: Drillin 13. Describe proposed or completed operations. (Clearly state all pertinent details, and	ALTERING CASING LLING OPNS. P AND A DOMESTICATION DEPT. PAND A DOMESTICATIO
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORL TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT OTHER: OTHER: Drillin 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At	ALTERING CASING LLING OPNS. P AND A D GOPERATIONS STATEMENT AND STATEMEN
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT OTHER: OTHER: Drillin 13. Describe proposed or completed operations. (Clearly state all pertinent details, and	ALTERING CASING LLING OPNS. P AND A DOB DEPARTMENT OF THE PROPERTY OF THE PROP
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIPULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENTOTHER: OTHER: Drillin 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 06/30/06 MIRU. Notified OCD of intent to spud. Spud 17 1/2" hole.	ALTERING CASING LLING OPNS. P AND A DOB DEPARTMENT OF THE PROPERTY OF THE PROP
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT OTHER: OTHER: Drillin 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 06/30/06 MIRU. Notified OCD of intent to spud. Spud 17 ½" hole. 07/01/06 TD 17 ½" hole @ 406".	ALTERING CASING LLING OPNS. P AND A JOB G Operations G igive pertinent dates, including estimated date tach wellbore diagram of proposed completion
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 06/30/06 MIRU. Notified OCD of intent to spud. Spud 17 ½" hole. 07/01/06 TD 17 ½" hole @ 406'. 07/02/06 Ran in 9 jts 13 3/8", 48# H-40 ST&C csg @ 406'. Cmt w/175 sx Cl C, tail w/250 sx Cl C. Circ 19	ALTERING CASING LLING OPNS. P AND A JOB G Operations G igive pertinent dates, including estimated date tach wellbore diagram of proposed completion
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 06/30/06 MIRU. Notified OCD of intent to spud. Spud 17 ½" hole. 07/01/06 TD 17 ½" hole @ 406'. 07/02/06 Ran in 9 jts 13 3/8", 48# H-40 ST&C csg @ 406'. Cmt w/175 sx Cl C, tail w/250 sx Cl C. Circ 807/03/06 Test csg to 250 & 1000 psi for 30 min – ok.	ALTERING CASING LLING OPNS. P AND A DO
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRI COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENTOTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 06/30/06 MIRU. Notified OCD of intent to spud. Spud 17 ½" hole. 07/01/06 TD 17 ½" hole @ 406". 07/02/06 Ran in 9 jts 13 3/8", 48# H-40 ST&C csg @ 406". Cmt w/175 sx Cl C, tail w/250 sx Cl C. Circ & 07/03/06 Test csg to 250 & 1000 psi for 30 min – ok. 07/11/06 TD 12 1/4" hole @ 4510". Ran 12 jts 9 5/8" 40# HCK-55 & 90 jts 9 5/8" 40# J-55 LT&C csg set	ALTERING CASING LLING OPNS. P AND A DO DE LLING OPNS. P AND A DO DE LLING OPNS. P AND A DO DE LLING OPNS. DE LL
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 06/30/06 MIRU. Notified OCD of intent to spud. Spud 17 ½" hole. 07/01/06 TD 17 ½" hole @ 406'. 07/02/06 Ran in 9 jts 13 3/8", 48# H-40 ST&C csg @ 406'. Cmt w/175 sx Cl C, tail w/250 sx Cl C. Circ 8 07/03/06 Test csg to 250 & 1000 psi for 30 min – ok. 07/11/06 TD 12 1/4" hole @ 4510'. Ran 12 jts 9 5/8" 40# HCK-55 & 90 jts 9 5/8" 40# J-55 LT&C csg set 2nd lead w/700 sx Class C cmt, tail w/250 sx 60:40 Cl C. Circulated 470 sx to reserve pit. OCD 6 07/13/06 Test csg to 1000 psi for 30 min – ok.	ALTERING CASING LLING OPNS. P AND A DO DE LLING OPNS. P AND A DO DE LLING OPNS. P AND A DO DE LLING OPNS. DE LL
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 06/30/06 MIRU. Notified OCD of intent to spud. Spud 17 ½" hole. 07/01/06 TD 17 ½" hole @ 406". 07/02/06 Ran in 9 jts 13 3/8", 48# H-40 ST&C csg @ 406". Cmt w/175 sx Cl C, tail w/250 sx Cl C. Circ & 07/03/06 Test csg to 250 & 1000 psi for 30 min – ok. 07/11/06 TD 12 1/4" hole @ 4510". Ran 12 jts 9 5/8" 40# HCK-55 & 90 jts 9 5/8" 40# J-55 LT&C csg set 2nd lead w/700 sx Class C cmt, tail w/250 sx 60:40 Cl C. Circulated 470 sx to reserve pit. OCD 07/13/06 Test csg to 1000 psi for 30 min – ok. 08/20/06 TD 8 ¾" hole @ 12,336".	ALTERING CASING LLING OPNS. P AND A DOB DOB DE
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 06/30/06 MIRU. Notified OCD of intent to spud. Spud 17 ½" hole. 07/01/06 TD 17 ½" hole @ 406". 07/02/06 Ran in 9 jts 13 3/8", 48# H-40 ST&C csg @ 406". Cmt w/175 sx Cl C, tail w/250 sx Cl C. Circ 8/07/03/06 Test csg to 250 & 1000 psi for 30 min – ok. 07/11/06 TD 12 1/4" hole @ 4510". Ran 12 jts 9 5/8" 40# HCK-55 & 90 jts 9 5/8" 40# J-55 LT&C csg set 2nd lead w/700 sx Class C cmt, tail w/250 sx 60:40 Cl C. Circulated 470 sx to reserve pit. OCD 07/13/06 Test csg to 1000 psi for 30 min – ok. 08/20/06 TD 8 ¾" hole @ 12,336". 08/21/06 Ran 309 jts 5 ½" 17#, P-110H LT&C csg set @ 12.336'. Cement first stage w/1000 sx 15:61 Po	ALTERING CASING LLING OPNS. P AND A DOB DOB DE
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 06/30/06 MIRU. Notified OCD of intent to spud. Spud 17 ½" hole. 07/01/06 TD 17 ½" hole @ 406". 07/02/06 Ran in 9 jts 13 3/8", 48# H-40 ST&C csg @ 406". Cmt w/175 sx Cl C, tail w/250 sx Cl C. Circ & 07/03/06 Test csg to 250 & 1000 psi for 30 min – ok. 07/11/06 TD 12 1/4" hole @ 4510". Ran 12 jts 9 5/8" 40# HCK-55 & 90 jts 9 5/8" 40# J-55 LT&C csg set 2nd lead w/700 sx Class C cmt, tail w/250 sx 60:40 Cl C. Circulated 470 sx to reserve pit. OCD 07/13/06 Test csg to 1000 psi for 30 min – ok. 08/20/06 TD 8 ¾" hole @ 12,336".	ALTERING CASING LLING OPNS. P AND A DOB DOB DE
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRI COMMENCE DRI CHANGE PLANS COMMENCE DRI CASING/CEMENT CASING MULTIPLE COMPL CASING/CEMENT CASING/CEMENT OTHER: Drillin 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 06/30/06 MIRU. Notified OCD of intent to spud. Spud 17 ½" hole. 07/01/06 TD 17 ½" hole @ 406'. 07/02/06 Ran in 9 jts 13 3/8", 48# H-40 ST&C csg @ 406'. Cmt w/175 sx Cl C, tail w/250 sx Cl C. Circ & 07/03/06 Test csg to 250 & 1000 psi for 30 min – ok. 07/11/06 TD 12 1/4" hole @ 4510". Ran 12 jts 9 5/8" 40# HCK-55 & 90 jts 9 5/8" 40# J-55 LT&C csg set 2nd lead w/700 sx Class C cmt, tail w/250 sx 60:40 Cl C. Circulated 470 sx to reserve pit. OCD 07/13/06 Test csg to 1000 psi for 30 min – ok. 08/20/06 TD 8 ¾" hole @ 12,336'. 08/21/06 Ran 309 jts 5 ½" 17#, P-110H LT&C csg set @ 12.336'. Cement first stage w/1000 sx 15:61 Po 60:40 Poz H. WOC 24 hrs.	ALTERING CASING LLING OPNS. P AND A DOB DOB DE
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRI COMMENCE DRI CHANGE PLANS COMMENCE DRI CASING/CEMENT CASING MULTIPLE COMPL CASING/CEMENT CASING/CEMENT OTHER: Drillin 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 06/30/06 MIRU. Notified OCD of intent to spud. Spud 17 ½" hole. 07/01/06 TD 17 ½" hole @ 406'. 07/02/06 Ran in 9 jts 13 3/8", 48# H-40 ST&C csg @ 406'. Cmt w/175 sx Cl C, tail w/250 sx Cl C. Circ & 07/03/06 Test csg to 250 & 1000 psi for 30 min – ok. 07/11/06 TD 12 1/4" hole @ 4510". Ran 12 jts 9 5/8" 40# HCK-55 & 90 jts 9 5/8" 40# J-55 LT&C csg set 2nd lead w/700 sx Class C cmt, tail w/250 sx 60:40 Cl C. Circulated 470 sx to reserve pit. OCD 07/13/06 Test csg to 1000 psi for 30 min – ok. 08/20/06 TD 8 ¾" hole @ 12,336'. 08/21/06 Ran 309 jts 5 ½" 17#, P-110H LT&C csg set @ 12.336'. Cement first stage w/1000 sx 15:61 Po 60:40 Poz H. WOC 24 hrs.	ALTERING CASING LLING OPNS. P AND A DOB DOB DE
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRI COMMENCE DRI CHANGE PLANS COMMENCE DRI CASING/CEMENT CASING MULTIPLE COMPL CASING/CEMENT CASING/CEMENT OTHER: Drillin 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 06/30/06 MIRU. Notified OCD of intent to spud. Spud 17 ½" hole. 07/01/06 TD 17 ½" hole @ 406'. 07/02/06 Ran in 9 jts 13 3/8", 48# H-40 ST&C csg @ 406'. Cmt w/175 sx Cl C, tail w/250 sx Cl C. Circ & 07/03/06 Test csg to 250 & 1000 psi for 30 min – ok. 07/11/06 TD 12 1/4" hole @ 4510". Ran 12 jts 9 5/8" 40# HCK-55 & 90 jts 9 5/8" 40# J-55 LT&C csg set 2nd lead w/700 sx Class C cmt, tail w/250 sx 60:40 Cl C. Circulated 470 sx to reserve pit. OCD 07/13/06 Test csg to 1000 psi for 30 min – ok. 08/20/06 TD 8 ¾" hole @ 12,336'. 08/21/06 Ran 309 jts 5 ½" 17#, P-110H LT&C csg set @ 12.336'. Cement first stage w/1000 sx 15:61 Po 60:40 Poz H. WOC 24 hrs.	ALTERING CASING LLING OPNS. P AND A DOB DOB DE
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRI COMMENCE DRI CHANGE PLANS COMMENCE DRI CASING/CEMENT CASING MULTIPLE COMPL CASING/CEMENT CASING/CEMENT OTHER: Drillin 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 06/30/06 MIRU. Notified OCD of intent to spud. Spud 17 ½" hole. 07/01/06 TD 17 ½" hole @ 406'. 07/02/06 Ran in 9 jts 13 3/8", 48# H-40 ST&C csg @ 406'. Cmt w/175 sx Cl C, tail w/250 sx Cl C. Circ & 07/03/06 Test csg to 250 & 1000 psi for 30 min – ok. 07/11/06 TD 12 1/4" hole @ 4510". Ran 12 jts 9 5/8" 40# HCK-55 & 90 jts 9 5/8" 40# J-55 LT&C csg set 2nd lead w/700 sx Class C cmt, tail w/250 sx 60:40 Cl C. Circulated 470 sx to reserve pit. OCD 07/13/06 Test csg to 1000 psi for 30 min – ok. 08/20/06 TD 8 ¾" hole @ 12,336'. 08/21/06 Ran 309 jts 5 ½" 17#, P-110H LT&C csg set @ 12.336'. Cement first stage w/1000 sx 15:61 Po 60:40 Poz H. WOC 24 hrs.	ALTERING CASING LLING OPNS. P AND A DOB DOB DE
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON	ALTERING CASING LLING OPNS. P AND A DOB
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRI COMMENCE DRI CHANGE PLANS COMMENCE DRI CASING/CEMENT CASING MULTIPLE COMPL CASING/CEMENT CASING/CEMENT OTHER: Drillin 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 06/30/06 MIRU. Notified OCD of intent to spud. Spud 17 ½" hole. 07/01/06 TD 17 ½" hole @ 406'. 07/02/06 Ran in 9 jts 13 3/8", 48# H-40 ST&C csg @ 406'. Cmt w/175 sx Cl C, tail w/250 sx Cl C. Circ & 07/03/06 Test csg to 250 & 1000 psi for 30 min – ok. 07/11/06 TD 12 1/4" hole @ 4510". Ran 12 jts 9 5/8" 40# HCK-55 & 90 jts 9 5/8" 40# J-55 LT&C csg set 2nd lead w/700 sx Class C cmt, tail w/250 sx 60:40 Cl C. Circulated 470 sx to reserve pit. OCD 07/13/06 Test csg to 1000 psi for 30 min – ok. 08/20/06 TD 8 ¾" hole @ 12,336'. 08/21/06 Ran 309 jts 5 ½" 17#, P-110H LT&C csg set @ 12.336'. Cement first stage w/1000 sx 15:61 Po 60:40 Poz H. WOC 24 hrs.	ALTERING CASING LLING OPNS. P AND A DOB
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRI TEMPORARILY ABANDON MULTIPLE COMPL CASING/CEMENTOLE DRILL OR ALTER CASING MULTIPLE COMPL CASING/CEMENTOLE DRILL OR ALTER CASING MULTIPLE COMPL CASING/CEMENTOLE DRILL DR	ALTERING CASING LLING OPNS. P AND A DO DE LLING OPNS. DE LLING OPNS
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON	ALTERING CASING LLING OPNS. P AND A DOB
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI CASING/CEMENTON MULTIPLE COMPL CASING/CEMENTON THER: Drillin 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 06/30/06 MIRU. Notified OCD of intent to spud. Spud 17 ½" hole. 07/10/106 TD 17 ½" hole @ 406'. 07/02/06 Ran in 9 jts 13 3/8", 48# H-40 ST&C csg @ 406'. Cmt w/175 sx Cl C, tail w/250 sx Cl C. Circ 307/03/06 Test csg to 250 & 1000 psi for 30 min – ok. 07/11/06 TD 12 1/4" hole @ 4510". Ran 12 jts 9 5/8" 40# HCK-55 & 90 jts 9 5/8" 40# J-55 LT&C csg set	ALTERING CASING LLING OPNS. PAND A JOB GOPERATION GOPERATION GOPERATION GOPERATION GOPERATION GOPERATION GOPERA
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRI TEMPORARILY ABANDON MULTIPLE COMPL COMMENCE DRI CASING/CEMENTOTHER: DOTHER: Drillin CASING/CEMENTOTHER: DOTHER: Drillin 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 06/30/06 MIRU. Notified OCD of intent to spud. Spud 17 ½" hole. 07/01/06 TD 17 ½" hole @ 406'. 07/02/06 Ran in 9 jts 13 3/8", 48# H-40 ST&C csg @ 406'. Cmt w/175 sx Cl C, tail w/250 sx Cl C. Circ 307/03/06 Test csg to 250 & 1000 psi for 30 min – ok. 07/11/06 TD 12 1/4" hole @ 4510". Ran 12 jts 9 5/8" 40# HCK-55 & 90 jts 9 5/8" 40# J-55 LT&C csg set 2nd lead w/700 sx Class C cmt, tail w/250 sx 60:40 Cl C. Circulated 470 sx to reserve pit. OCD 07/13/06 Test csg to 1000 psi for 30 min – ok. 08/20/06 TD 8 ¾" hole @ 12,336'. 08/21/06 Ran 309 jts 5 ½" 17#, P-110H LT&C csg set @ 12.336'. Cement first stage w/1000 sx 15:61 Po 60:40 Poz H. WOC 24 hrs. 08/22/06 Rig rlsd. I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will beconstructed or closed according to NMOCD guidelines a general permit SIGNATURE TITLE Sr. Staff Engineering Tec	ALTERING CASING LLING OPNS. PAND A JOB Signory PAND A g Operations Signory Pand A
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON	ALTERING CASING LLING OPNS. PAND A JOB Signory PAND A g Operations Signory Pand A
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRI TEMPORARILY ABANDON MULTIPLE COMPL COMMENCE DRI CASING/CEMENTOTHER: DOTHER: Drillin CASING/CEMENTOTHER: DOTHER: Drillin 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 06/30/06 MIRU. Notified OCD of intent to spud. Spud 17 ½" hole. 07/01/06 TD 17 ½" hole @ 406'. 07/02/06 Ran in 9 jts 13 3/8", 48# H-40 ST&C csg @ 406'. Cmt w/175 sx Cl C, tail w/250 sx Cl C. Circ 307/03/06 Test csg to 250 & 1000 psi for 30 min – ok. 07/11/06 TD 12 1/4" hole @ 4510". Ran 12 jts 9 5/8" 40# HCK-55 & 90 jts 9 5/8" 40# J-55 LT&C csg set 2nd lead w/700 sx Class C cmt, tail w/250 sx 60:40 Cl C. Circulated 470 sx to reserve pit. OCD 07/13/06 Test csg to 1000 psi for 30 min – ok. 08/20/06 TD 8 ¾" hole @ 12,336'. 08/21/06 Ran 309 jts 5 ½" 17#, P-110H LT&C csg set @ 12.336'. Cement first stage w/1000 sx 15:61 Po 60:40 Poz H. WOC 24 hrs. 08/22/06 Rig rlsd. I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will beconstructed or closed according to NMOCD guidelines a general permit SIGNATURE TITLE Sr. Staff Engineering Tec	ALTERING CASING LLING OPNS. PAND A JOB GOPERATION GOPERATION GOPERATION GOPERATION GOPERATION GOPERATION GOPERA