Submit 3 Copies To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505		Form C-103 May 27, 2004
District 1 1625 N. French Dr., Hobbs, NM 88240			/ELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210			0-015-27559
District III			Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV			State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			708
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		.S 7.	Lease Name or Unit Agreement Name
		COD CHICH	
PROPOSALS.)	<u> </u>		EV" State Com . Well Number 2
1. Type of Well: Oil Well			
2. Name of Operator Dominion Oklahoma E&P, Inc			9. OGRID Number 025773
3. Address of Operator			10. Pool name or Wildcat
14000 Quail Springs Parkway, Suite 600, Oklahoma City, OK 73134			Happy Valley (Morrow)
4. Well Location			
Unit Letter <u>H</u>	: 2100 feet from the No	rth line and 66	0 feet from the <u>East</u> line
Section 32	Township 22S	Range 26E	NMPM Eddy County
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3320' (GL)			
Pit or Below-grade Tank Application		•	
Pit type Depth to Groundwater150' _Distance from nearest fresh water well1/4 mile Distance from nearest surface water>1/4 mile			
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WORK			☐ ALTERING CASING ☐
TEMPORARILY ABANDON		COMMENCE DRILLI	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT JO	OB 🗌
OTHER:		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion. P&A wellbore- See attached procedure.			
-			
Estimated Start Time- 11/01/06			
I hereby certify that the information	above is true and complete to the	best of my knowledge ar	nd belief. I further certify that any pit or below- in (attached) alternative OCD-approved plan
Will not use pits. Will use above		: <u>—</u> , а general регин <u>—</u> өг а	in (attached) afternative OCD-approved plan [_].
SIGNATURE Talm C.	CALLETTILE_	Production Engineer	DATE10/19/65
Type or print name Patricia Culpe	epper E-mail address: Patri	cia_M_Culpepper@dom	a.com Telephone No. 405-753-7513
Man Marie Use Omy	- 0	1 - 4	
APPROVED BY:	whi TITLET	wofy	DATE 10/31/06
Conditions of Approval (if any):			
			DATE 10/3/ 06
			7520-

Notify OCD 24 hrs. prior to any work done.




RE: E.V. STATE COM #2 Eddy County, NM

- (1) Move in and rig up.
- (2) Nipple down wellhead. Nipple up BOP.
- (3) Release pkr. Pull out of hole w/ tubing and packer. Stand tubing in derrick.
- (4) Rig up wireline. Set bridge plug in liner top at 11,100'.
- (5) Cap bridge plug w/ 2 sx cement...
- (6) Set 7" Bridge plug @10,400'.
- (7) Run in hole with tubing 10,400'.
- (8) Mix & circulate mud.
- (9) Spot 25 sx. cmt. Cap bridgeplug.
- (10) Pull up hole. to 8,650'. Spot 40 sx. of cmt.
- (11) Pull up hole to 5,660'. Spot 30 sx. cmt.
- (12) Pull up hole to 3,800'. Spot 40 sx. cmt.
- (13) Pull out of hole w/ tubing. .
- (14) Perf. 95/8" shoe 1,706".
- (15) Run in hole w/ packer. Sqz. 75 sx. cmt. W.O.C. to tag.
- (16) Pull out of hole w/ packer.
- (17) Run in hole to 420°. Spot 50 sx. cmt. TAC
- (18) Spot 10 sx. surface.
- (19) Rig down. Move out.

enday control of the control were consistent with the control of t

32-22S-26E HAPPY VALLEY Field EDDY County, NM API # 30015275590000 /CC 4340,001



32-22S-26E HAPPY VALLEY Field EDDY County, NM API # 30015275590000 /CC 4340.001

