

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
May 27, 2004

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-015-05712
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E 6018
7. Lease Name or Unit Agreement Name: STATE
8. Well Number 1
9. OGRID Number 018862
10. Pool name or Wildcat SHUGART

SUNDRY NOTICES AND REPORTS ON WELL  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	2. Name of Operator RAY WESTALL
3. Address of Operator BOX 4, LOCO HILLS, NM 88255	4. Well Location Unit Letter C : 330 feet from the NORTH line and 1650 feet from the WEST line Section 2 Township 19S Range 31E NMPM County EDDY, NM
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3626 TH	
Pit or Below-grade Tank Application <input type="checkbox"/> or Closure <input type="checkbox"/> Pit type STEEL Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material	

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>
OTHER: <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

10-4-06 Spot 25 sx. cmt. @2,800'.

10-5-06 Plug @2,630'. Circulate hole with mud. Spot 25 sx. cmt. @2,450'. Tag Plug @2,117'. Perf 4 holes @960'. Set pkr. @560'. Squeeze 40 sx. cmt. Tag plug @810'. Perf. 4 holes @60'. Pump 15 sx. cmt. down 4 1/2" to surface out of 8 5/8". Leave 4 1/2" full of cement.

10-6-06 Install Dryhole Marker.

Approved as to plugging of the well bore. Liability under bond is retained until surface restoration, environmental remediation and final inspection is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. A below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ , a g

SIGNATURE Randall Minear TITLE P & A Supervisor DATE 10-9-06

Type or print name RANDALL MINEAR

E-mail address:

Telephone No. 432-530-0907

For State Use Only

APPROVED BY Gerry Guye TITLE Deputy Field Inspector DATE OCT 20 2006

Conditions of Approval, if any: