

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

S

SOIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.

30-015-05713

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

E 6018

7. Lease Name or Unit Agreement Name:

STATE

8. Well Number

2

9. OGRID Number

018862

10. Pool name or Wildcat

SHUGART

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

RAY WESTALL

3. Address of Operator

P.O. BOX 4, LOCO HILLS, NM 88255

4. Well Location

Unit Letter B : 330 feet from the NORTH line and 2310 feet from the EAST line

Section 2 Township 19S Range 31E NMPM County EDDY

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3626 GL

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type STEEL Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion.

Approved as to plugging of the well bore. Liability under bond is retained until surface restoration, environmental remediation and final inspection is completed.

10-12-06 Set 4 1/2" CIBP @2,686'. Cap w/35' cmt. w/bailer. Circulate hole with mud. Perf 4 holes @2,475'. Set pkr. @2,000'. Sqz. 40 sx. cmt.

10-13-06 No tag on plug @2,475'. Sqz. 40 sx. cmt. @2,475'.

10-16-06 Tag plug @2,280'. Perf. 4 holes @960'. Set pkr. @660'. Sqz. 40 sx. cmt. Tag plug @823' Perf. 4 holes @60'. Pump 20 sx. cmt. down 4 1/2" to surf. out of 8 5/8". Leave 4 1/2" full of cmt. 10-17-06 Install Dry Hole Marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE Dusty Roach TITLE AREA MANAGER DATE 10-24-06

E-mail address:

Type or print name DUSTY ROACH

Telephone No.

For State Use Only

APPROVED BY Jim W. Green TITLE District II Supervisor DATE 11/6/06

Conditions of Approval, if any: