Form 3160-5 (April 2004)

3a Address

TYPE OF SUBMISSION

Notice of Intent

Final Abandonment Notice

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENTO

SUBMIT IN TRIPLICATE- Other instructions on

2. Name of Operator CHESAPEAKE OPERATING, INC.

P. O. BOX 18496, OKLAHOMA CITY, OK 73154-0496

4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1920 FNL & 660 FWL, SWNW, SECTION 27-18S-31E

SUNDRY NOTICES AND REPORTS ON

DEPARTMENT OF THE INTERIOR ECEIVED BUREAU OF LAND MANAGEMENTO ARTES SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drills or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.	FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007 5. Lease Serial No. NMLC-29392B 6. If Indian, Allottee or Tribe Name					
JBMIT IN TRIPLICATE- Other instructions on reverse side.	7. If Unit or CA/Agreement, Name and/or No.					
Oil Well Gas Well Other	8. Well Name and No.					
Tator CHESAPEAKE OPERATING, INC. ATTN: LINDA GOOD	Principle Federal 4 9. API Well No.					
3b. Phone No. (include area code) 405-767-4275	30-015-32894					
Vell (Footage, Sec., T., R., M., or Survey Description)	10. Field and Pool, or Exploratory Area Shugart 11. County or Parish, State Eddy County, New Mexico					
660 FWL, SWNW, SECTION 27-18S-31E						
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, I	REPORT, OR OTHER DATA					
SUBMISSION TYPE OF ACTION	TYPE OF ACTION					
Acidize Deepen Production (Standard Reclamation Alter Casing Fracture Treat Reclamation Recomplete Change Plans Plug and Abandon Temporarily Andonment Notice Convert to Injection Plug Back Water Disposal	Well Integrity Other bandon					

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Chesapeake, respectfully, request permission to TA this well. We plan to lay out the rods and tubing, set a CIBP @ 6100', load and pressure test the casing for a MIT. We intend to review the wellbore for additional recompletion potential uphole within the next 12 months.

Attached is the wellbore diagram.

Accepted for record

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

(CHK PN 890591)

Approval given to perform MIT, subsequent sundry required for actual TA approval. See attached conditions of approval,

 I hereby certify that the foregoing is true and correct Name (Printed/Typed) 	ı					
LINDA GOOD Title PERMITTING AGENT						
Signature Rinda Good	Date	10/26/200	ľ	APPR	POVED	-
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved by		Title	Dat	NOV	2 2006	
Conditions of approval, if any, are attached. Approval of this notice does not warracertify that the applicant holds legal or equitable title to those rights in the subject lewhich would entitle the applicant to conduct operations thereon.		Office			LGRAM WINGRAM	,
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212 make it a crime for any	v nerson	knowingly and willfully to make t	any d		M PNGINEER	ł

CURRENT WELLBORE SCHEMATIC CHESAPEAKE OPERATING INC.

WELL

: PRINCIPLE FEDERAL #4

LOCATION

: 1920' FNL & 660' FWL, SEC. 27-T18S-R31E

COUNTY

: EDDY

STATE: NM

FIELD

: SHUGART DELAWARE

ELEVATION: 3,632' GL

3,645' KB

API#:

30-015-32894

Chesapeake

SPUD DATE:

12/03/03

COMPL. DATE:

1/21/04

CHK#

890591

Hole Size

Well History:

1/09/03: Ran CBL/GR/CCL. TOC @ 1,480'. Perfd Delaware @ 6,140-60', 6,168-80', 6,198-202', &

6,210-222', w/ 2 jspf & 100 holes.

1/13/03; Acidz perfs w/ 5,--- gals 7 1/2% 90/10 acid

using 150 BS to divert.

9-5/8" 40# J-55 LT & C csq. @ 647.58:

Cmt w/ 100 sx 65/35 Poz C + 6% gel, 2% CaCl2 + linked gel carrying 86,000# 16/30 white sand & 18,000 to 100 st linked gel carrying 86,000# 16/30 white sand & 18,000 16/30 Super LC resin coated sand.

1/21/04; RIH w/ 196 jts 2-7/8" J55 EUE 8 rd tbg set

@ 6,126'

1/22/04: RIH w/ 2-1/2" x 1-1/2" x 24' RHNM pmp.


Began testing well.

1/30/04: Chesapeake took over operations from

Concho.

2/04/04: 1st gas sales 0 BO, 341 BW, 32 MCFG.

7/30/06: P: 0 BO 144 BW 0 MCFG FTP 200#



PBTD @ 6,315'

PREPARED BY: Renee Thomas DATE: ___ 2/18/05 (AM) Lorie Higginbotham 8/2/06 UPDATED BY:___ DATE:_

50/50 Poz C + 5% salt + .08% FL-52 + .03% SMS.

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 505-234-5972

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 505-234-5972; Lea County 505-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.

Wells that successfully pass the casing integrity test will be approved for Temporary Abandonment (TA) status for a 12 month period provided that the operator:

- Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.

The TA status could be extended for an additional 12 month period without another casing integrity test provided there was no leak-off during the test and the test was witnessed by a BLM representative. The operator must submit a sundry notice requesting an extension of TA status 30 days prior to expiration of the previous approval and appropriate justification for extending the TA status is included.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.