

Submit 3 Copies To Appropriate District
 Office
 District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 1301 W. Grand Avenue, Artesia, NM 88210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-103
 Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-28288
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator Chevron USA, Inc.		6. State Oil & Gas Lease No.
3. Address of Operator 15 Smith Rd. Midland, Tx 79705		7. Lease Name or Unit Agreement Name: Murchison State Oil & Gas Lease
4. Well Location Unit Letter <u>H</u> 1980 feet from the <u>North</u> line and <u>660</u> feet from the <u>East</u> line Section <u>2</u> Township <u>25-S</u> Range <u>26-E</u> NMPM County <u>Eddy</u>		8. Well No. 1
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. Pool name or Wildcat Black River, Delaware South

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐ OTHER: ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐ CASING TEST AND CEMENT JOB ☐ OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Notify OCD 24hrs prior to MI & RU.
2. Set 5 1/2 CIBP@2980, spot 25sx plug 2980-2700(Delaware)WOC Tag.
3. Displace hole w/MLF, 9.5# Brine w/25# Gel P/BBL.
4. Perf 4 holes @ 2060, sqz 50sx plug 2060-1900(8 5/8 shoe, B-salt)WOC Tag.
5. Perf 4 holes @ 625, sqz 250sx plug 625-200(13 3/8 shoe, T-salt)WOC Tag.
- 6 10 sx surf, Install dry hole marker. — WOC-24 hrs- TAG-

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE D. B. Bledsoe TITLE HES Specialist DATE 8-12-03

Type or print name G. R. Bledsoe
 (This space for State use)

Telephone No. (432) 687-7153

APPROVED BY [Signature] TITLE Wild Dog ID DATE APPROVED AUG 28 2003

Conditions of approval, if any: