

FORM APPROVED
OMB No. 1004-0137
Expires: March 31, 2007

(Instructions on page 2)

**Midnight Matador #6
Fairway Resources Operating, LLC
December 6, 2006
Conditions of Approval**

Rubbers should be installed on the drill pipe collars to keep from wearing through the 25-30% thinner wall of this pipe.

WWI 120606