Submit 3 Copies To Appropriate District Office	State of New Me		Form C-103 May 27, 2004
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Energy, Minerals and Natural Resources		WELL API	NO
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION		DIVISION JO C	Type of Lease
District III 1220 South St. Francis Dr.			TE K FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505			& Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		В93	91
SUNDRY NOT	TICES AND REPORTS ON WELLS OSALS TO DRILL OR TO DEEPEN OR MILICATION FOR PERMIT" (FORM C-101), F	NERPASK TO A	me or Unit Agreement Name
PROPOSALS.) 1. Type of Well: Oil Well X Gas Well Other OCD - ARTEMA COST.		9 Well Nur	
2. Name of Operator		9. OGRID I	
H & S Oil, LLC		0095	72
3. Address of Operator	O D 106 A ND		me or Wildcat
4. Well Location	O. Box 186, Artesia, N	1 88211-0180 Z M	pini Abo
1	: 1980 feet from the North	line and 660 fe	et from the East line
Section 2	Township 18S R		County Eddy
A The Addition of the Control of the	11. Elevation (Show whether DR		1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1
3,592 GR			
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water			
Pit Liner Thickness: m		bbls; Construction Mate	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
12. Check Appropriate box to mulcate mature of mouce, Report of Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ARANDON ALTERING CASING CA			
TEMPORARILY ABANDON [PULL OR ALTER CASING [☐ CHANGE PLANS ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	COMMENCE DRILLING OPNS CASING/CEMENT JOB	. PANDA
TOLE ON ALTEN OAGING	7 MOELII EE OOME E	CACHACIOLINEIT 100	U .
OTHER:		OTHER:	
	apleted operations. (Clearly state all work). SEE RULE 1103. For Multip		
Estimated Starting	Data: 03/01/07 (dapar	nding on availability	of pulling unit)
Estimated Starting Date: 03/01/07 (depending on availability of pulling unit) 1. Drill out CIBP & 1 Sx. Cement @ 5575'			
2. Clean out $4\frac{1}{2}$ " Casing to 6000'			
3. Swab test old perfs: 5832-5842, 5866-5870, & 5956-5962			
4. Perforate new holes: 5760-5778'			
 Acidize all perfs w/5000 gals. 15% Nefe Swab test all perfs 			
o. Swab test all peris			
_	. 1	•	
Open to use	Dressure Control d	2016	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be/constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.			
$\frac{1}{2}$			
SIGNATURE New TITLE Managing Member/Operator DATE 1/31/07 Herbert R. Spencer			
Type or print name	Spencer E-mail a	ddress: hsoillic@	Telephone No. 505-746-6658
For State Use Only BRYA		Blateautel.net	
DISTI	N G. ARRANT	praceaucer. He	Ern
APPROVED BY:	N G. ARRANT RICT II GEOLOGIST TITLE	praceaucer.net	FEB 0 5 2007