OCD-ARTESIA

UNITED STATES
DEPARTMENT OF THE INTERIOR

Form 3160-5 (April 2004)

FORM APPROVED
OM B No. 1004-0137
Expires: March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS				5. Lease Serial No. NM 108988		
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE- Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well Officer Officer				O Well Name	· ·	
2. Name of Operator MURCHISON OIL & GAS, INC.				8. Well Name and No. DAINWOOD DRAW FED 4#1		
3a Address 3b. Phone No. (include area code)				9. API Well No. 30-015-35175		
1100 MIRA VISTA BLVD., PLANO, TX. 75093-4698 972-931-0700				10. Field and Pool, or Exploratory Area WILDCAT WOLFCAMP		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) SURF. LOC: 660' FSL & 860' FEL SEC. 4, T17S, R23E BHL: 760' FNL & 760' FEL SEC. 4, T17S, R23E				11. County or Parish, State EDDY CO., NM.		
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA						
TYPE OF SUBMISSION		TY	PE OF ACTION			
☐ Notice of Intent ✓ Subsequent Report ☐ Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (Sta Reclamation Recomplete Temporarily Ab	. ,	Water Shut-Off Well Integrity Other RUN 7-5/8" CSG	
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) Drill 8-3/4" hole to 3100'. Run 75 jts. of 7-5/8" 29.70 #/FT P-110 SJ2 Flush Jt. Set 7-5/8" casing @ 3100'. Cement with 350 SXS 50/50 POZ Class "C" + 10% D20 + 5 PPS D24 + .125 PPS D130 and tail with 300 SXS Class "C" + 2% S1 + .125 PPS D130. Plug down @ 10:00 AM. No cement to surface. WOC 5 Hrs. Pump 350 SXS "C" Neat down backside of 7-5/8". BLM's Rep. on location. WOC 5 Hrs. ND BOP's, set slips on 7-5/8". Install "C" Section and Test to 5000 PSI. PU 5000 PSI BOP and NU. Pump 350 SXS of "C" neat cement down 7-5/8" backside. WOC 3 Hrs. and run temp survey. Determined TOC @ 300'. Nipple up BOP. Test BOP to 5000 PSI. Test Hydrill to 1500 PSI. Held OK. Resume drilling w/ 6-1/2" bit.						
14. Thereby certify that the fore Name (Printed/Typed)	egoing is true and correct					
MICHAEL S. DAUGHERTY Title VICE PRESIDENT OPE					3	
Signature Machaell	THIS SPACE FOR	Date Date	TATE OFFICE	ACCE	PTED FOR RECORD	
	MIS STACE FOR	FEDERAL OR S	TATE OFFICE	USE		
Approved by			litle	D	JAN 2 4 2007	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.				WE	SLEY W. INGRAM	
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.						

(Instructions on page 2)

2/5/07