

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD-AR

S

FORM APPROVED
OMB No. 1004-0135
Expires January 31, 2004

Month - Year
FEB 20 2007
OCD - ARTESIA, NM

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or re enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.

NM-01165

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

Williamson BC #4

9. API Well No.

30-015-22049

10. Field and Pool, or Exploratory Area

Winchester-Upper Penn

11. County or Parish, State

Eddy County, New Mexico

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐

Oil Well

☐

Gas Well

☒

Other P&A

2. Name of Operator

Yates Petroleum Corporation

3a. Address

105 S. 4th Str., Artesia, NM 88210

3b. Phone No. (include area code)

505-748-1471

4. Location of Well (Footage, Sec., T., R., M., OR Survey Description)

1980'FSL & 1980'FWL of Section 7-T20S-R29E (Unit K, NESW)

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐

Notice of Intent

☒

Subsequent Report

☐

Final Abandonment Notice

☐

Acidize

☐

Alter Casing

☐

Casing Repair

☐

Change Plans

☐

Convert to Injection

☐

Deepen

☐

Fracture Treat

☐

New Construction

☒

Plug and Abandon

☐

Plug Back

☐

Production (Start/Resume)

☐

Reclamation

☐

Recomplete

☐

Temporarily Abandon

☐

Water Disposal

☐

Water Shut-Off

☐

Well Integrity

☐

Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof.

If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

6/21/06 Pumped 70 bbls brine down backside. Pumped 50 bbls brine down tubing and worked packer. Worked loose. Pumped 100 bbls brine.
6/22/06 RIH with bailer to 3688', got stuck.
6/23/06 Worked tubing and rotated and lower.
1/16/07 RIH with bailer and tagged at 3700'.
1/17/07 Washed and reamed 275 joints to 8932'.
1/18/07 Tagged at 10,122'.
1/22/07 Started circulating hole with plugging mud.
1/24/07 Spotted 25 sx Class "H" cement, WOC. Tagged at 9683'. Spotted 25 sx Class "H" cement at 9165', WOC.

Accepted for record

CONTINUED ON NEXT PAGE:

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

Tina Huerta

Title

Regulatory Compliance Supervisor

Signature

Tina Huerta

Date

February 1, 2007

THIS SPACE FOR FEDERAL OR STATE OFFICE USE


Approved by

Title

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction




Yates Petroleum Corporation
Williamson BC #4
Section 7-T20S-R29E
Eddy County, New Mexico
Page 2

Form 3160-5 continued:

1/25/07 Tagged at 8805'. Perforated at 7156'. Pumped 50 sx cement, WOC. Tagged at 6623'. Perforated at 5685'. Pumped 50 sx cement.
1/26/07 Tagged at 5440'. Perforated at 3685'. Pumped 50 sx cement, WOC. Tagged at 3166'.
1/29/07 Pull on 4-1/2" casing to get off slips. Casing jumped and came free. Tagged casing stub.
1/30/07 Could not get in. Called BLM - OK to spot plug. Spotted 100 sx cement at 3705', WOC. Tagged at 3521'. Spotted 150 sx cement at 2860', WOC. Tagged at 2454'. Spotted 150 sx cement at 1332', WOC.
1/31/07 Tagged at 935'. Spotted 50 sx cement at 650', WOC. Tagged at 490'. Pumped 50 sx cement at 162'. Cement circulated to surface. Cut off wellhead. Installed dry hole marker.

WELL IS PLUGGED AND ABANDONED. FINAL REPORT.

Please notify Jim Krogman (505-365-8340) 3 days prior to BLM inspection, so we have the opportunity to meet with the inspector on location to confirm all reclamation requirements before receiving the notice of written order.


Regulatory Compliance Supervisor
February 1, 2007