



UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD - ARTESIA

FORM APPROVED
OMB No. 1004-0137
Expires: March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160 - 3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

1. Type of Well Oil Well Gas Well Other

X

2. Name of Operator Nadel and Gussman Permian, LLC

3a. Address 601 N. Marienfeld, Suite 508
Midland, TX 797001

3b. Phone No. (include area code)
432-682-4429

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit Letter M: 660 feet from the South line and 660 feet from the West line of Section 22,
Township 24S, Range 28E

5. Lease Serial No. NM 20360

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

Aminoil Federal #3

9. API Well No.

30-015-35020

10. Field and Pool, or Exploratory Area

Morrow

11. County or Parish, State

Eddy County, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off
	Alter Casing	Fracture Treat	Reclamation	Well Integrity
X Subsequent Report	Casing Repair	New Construction	Recomplete	Other Run & Cement
	Change Plans	Plug and Abandon	Temporarily Abandon	Production Casing
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

2/2/07 Complete TOH. Well started flowing. Run 5 1/2" casing to 4000' and circulate gas out. Run casing to 10,200' and circulate pills and gas out. Run casing to 11,500' and circulate pills and gas out. Complete running casing to TD at 12,950' (1017' of 5 1/2"/20#/HCP110/LTC on bottom followed by 11,933' of 5 1/2"/17#/HCP110/LTC) and circulate pills and gas out.

2/3/07 Circulate and condition mud while continuing to circulate gas out and RU Schlumberger. Pumped 20 bbls Mud Clean II spacer, 72 bbls of 11.5 ppg 35/65 Poz Class H cement, 148 bbls of 12.7 ppg 35/65 Poz Class H cement and 106 bbls of 13.0 ppg TXI Lightweight cement. Displaced with 298 bbls of FW and bumped plug. Full returns throughout job and floats held. RD Schlumberger, ND BOPS, set slips, jet pits and release rig.

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed) Terry West

Title Engineer

Signature

Date

2-5-07

THIS SPACE FOR FEDERAL OR STATE OFFICE ACCEPTED FOR RECORD

Ar2rarcv~

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title

Date

Office

FEB 19 2007

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowing and willfully to make any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

FREDERICK WRIGHT
PETROLEUM ENGINEER

(Instructions on page 2)