

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

ATTACHMENT 1

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-015-25796

OPERATOR

☒ Initial Report ☐ Final Report



Name of Company ConocoPhillips Company	Contact Jesse A. Sosa	
Address 3300 N. "A" St., Bldg. 6 #247 Midland, TX 79705-5	Telephone No. (505)391-3126	
Facility Name Grayburg Deep Unit Well #10	Facility Type Gas Well	
Surface Owner BLM	Mineral Owner BLM	Lease No. LC028793A

LOCATION OF RELEASE

Unit Letter C	Section 19	Township 17S	Range 30E	Feet from the 660	North/South Line North	Feet from the 2480	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.49512 Longitude 104.00718

NATURE OF RELEASE

Type of Release Oil and Produced Water	Volume of Release 115	Volume Recovered 0
Source of Release 3 inch bullplug on tank	Date and Hour of Occurrence am 6/29/07	and Hour of Discovery 9am 7/2/07
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos (BLM) & Mike Bratser (NMOCD)	
By Whom? Jesse Sosa	Date and Hour 2 pm 07/02/2007	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* While making rounds MSO found contaminated area around tank. Contamination was caused by all fluids emptying out of tank due to half inch hole in 3 inch bullplug caused by internal corrosion. MSO had last checked location on Friday June 29, 2007 and fluid was still in tank.		
Describe Area Affected and Cleanup Action Taken.* HSE arrived on location and measured spill size affected area of 9 ft X 84 ft, all was inside diked and fenced area. Area will be delineated to determine necessary clean up actions.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jesse A. Sosa	Approved by District Supervisor: 	
Title: HSER Lead	Approval Date: AUG 7 2007 Expiration Date: 9-07-07	
E-mail Address: Jesse.A.Sosa@conocophillips.com	Conditions of Approval:	
Date: 07/02/2007 Phone: (505)391-3126	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

Work Plan on file