

OCD-ARTESIA

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB No 1004-0137
Expires March 31, 2007

OCD-ARTESIA

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1 Type of Well

☐ Oil Well ☒ Gas Well ☐ Other2 Name of Operator
Devon Energy Production Co., LP3a Address
20 North Broadway
OKC, OK 73102-82603b. Phone No. (include area code)
(405)-552-78024 Location of Well (Footage, Sec., T, R, M, or Survey Description)
NENW Lot C Sec 24-T22S-R25E
660' FNL & 1980' FWL5. Lease Serial No.
NMNM-96207

6. If Indian, Allottee or Tribe Name

7 If Unit of CA/Agreement, Name and/or No

8. Well Name and No
Filaree 24C Fed Com 49. API Well No.
30-015-3444610. Field and Pool or Exploratory Area
Happy Valley; Morrow11 Country or Parish, State
Eddy County, New Mexico

12 CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent☒ Subsequent Report☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize☐ Alter Casing☐ Casing Repair☐ Change Plans☐ Convert to Injection☐ Deepen☐ Fracture Treat☐ New Construction☐ Plug and Abandon☐ Plug Back☐ Production (Start/Resume)☐ Reclamation☐ Recomplete☐ Temporarily Abandon☐ Water Disposal☐ Water Shut-Off☐ Well Integrity☒ Other Add Morrow Pay

13 Describe Proposed or Completed Operation Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompletable horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletable in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

06/11/07 - 06/20/07:

MIRU. Bld well dwn. NU BOP, rls pkr & swab. TOH w/pkr. RIH & perf @ 10634 - 10636', 10650 - 10654', 10745' - 10756' (4SRF) 60' holes. WLL set pkr @ 10,580'. TIH w/ON/OFF tool & tbg. Land tbg, NU tree. Swab. Acidize morrow @ 10634 - 10756' w/15 gal 15% HCL acid w/200-ball slrs. Full open chk, flw bck Swab. Bld dn well, swab. RD/MO/WSU. Frac perfs @ 10634 - 10750' w/12000# sn. Swab. Return well to production.

AUG 14 2007

LES BABYAK
PETROLEUM ENGINEER

14 I hereby certify that the foregoing is true and correct.

Name (Printed/Typed)

Stephanie A. Ysasaga

Title Sr. Staff Engineering Technician

Signature

Date 06/29/2007

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

(Instructions on page 2)