Submit 3 Copies To Appropriate District Office		New Mexico		Form C-103	
District I 1625 N French Dr , Hobbs NM 88240	Energy, Minerals and Natural Resources		WELL AP	May 27, 2004 NO. 30-015-22398	
District II 1301 W Grand Ave. Aresia, JM 88210 District III	OIL CONSERVÁTION DIVISION 1220 South St. Francis Dr.			Type of Lease	
1000 Rio Brazos Rd., Azieg 149,87410 District IV	Santa Fe, NM 87505		6. State Oi	TE FEE X l & Gas Lease No.	
1220 S St. Francis Dr , Santa Fe, NM 87505			SRMA12		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease N BIG EDD	7. Lease Name or Unit Agreement Name BIG EDDY UNIT	
	Gas Well Other			8. Well Number 60	
2. Name of Operator BEPCO, L.P		AUG 2.9 2007	9. OGRID	Number 001801	
3. Address of Operator P.O. BOX	perator P.O. BOX 2760		a	10. Pool name or Wildcat	
4. Well Location	D, TX 79702-2760	- COD ARTESIA	FENTON	(BONE SPRING)	
Unit Letter J: 1980 feet from the SOUTH line and 1980 feet from the EAST line					
Section 20	Township 21S		NMPM	CountyEDDY	
Pit or Below-grade Tank Application ☐ o	11. Elevation (Show wh 3204.3' GL	ether DR, RKB, RT, GR	, etc.)		
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water					
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	ITENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL	☐ REMEDIAL \	WORK EDRILLING OPNS	T REPORT OF: ☐ ALTERING CASING ☐ S.☐ P AND A 🖾 ☐	
OTHER:		☐ OTHER:			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.					
MIRU plugging equipment and PU on 08/06/2007. POOH w2-3/8" tbg. 1- RIH with 5-1/2" CIBP set @ 6330'. Circulate wellbore with 150 bbls 10 ppg salt gel mud. 2- Spot 35 sxs "C" neat cement from 5985' to 6330'. Called Phil Hawkins w/ OCD.					
 3- Free point 5-1/2" casing. Cut casing at free point @ 3250". POH and lay down casing. 4- Spot 40 sxs Class "C" neat cement 3111' to 3258'. WOC and tag @ 3134'. 					
5- Spot 40 sxs Class "C" neat cement from 2800' to 2945'. 6- Spot 40 sxs Class "C" neat cement from 722' to 868'. DV Tool @ 800'. WOC & Tag cmt @ 720'					
7- Spot 40 sxs Class "C" neat cement from 443' to 590'. WOC & Tag cmt @ 466'. Phil Hawkins w/OCD called but did not witness. 8- Spot 40 sxs Class "C" neat cement from 227' to 373'					
9- Spot 20 sxs Class "C" neat cement from 0' to 95' from Surface.					
Cut off wellhead and install dry hole marker. Wellbore Plugged and Abandoned 08/15/2007. Plugging of the well bore. Liability under bond is retained					
until surface restoration,					
•	environmental remediation and				
		,	tinal inspass	s completed.	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines, a general permit or an (attached) alternative OCD-approved plan					
SIGNATURE $Q_{m}\gamma$	noole 1	TITLE PRODUCTION (CLERK	DATE 08/27/2007	
Type or print name ANN MOORE For State Use Only	1	E-mail address:camoore	ebasspet.com	Telephone No. (432)683-2277	

APPROVED BY: Middle TITLE on the DATE 3/2007 Conditions of Approval (if any):