Submit 3 Copies to Appropriate District Office

CONDITIONS OF APPROVAL, IF ANY:

## State of New Mexico Energy, Minerals and Natural Resources Department

	,			
<u>DISTRICT I</u> P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION		WELL API NO.	
1.0. 800 1300, 10003, 1111 00240	2040 Pacheco St	2506 29 3 s	30-015-2930	19
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, NM	720033037	sIndicate Type of Lea	
	Joint ,	\chi_{\chi_{\chi}} \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		STATE FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	/ <sub>2</sub> ?	1003	State Oil & Gas Leas	se No.
Tool the Brazos reign Electric tree		\$ 165 PM 22		
SUNDRY NO	TICES AND REPORTS ON WE	LISCURRIVE OF	112	14-15-4-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-
(DO NOT USE THIS FORM FOR PR	OPOSALS TO DRILL OR TO DEEPER	NOR-REUG BACK 10) A	₁Lease Name or Unit	Agreement Name
(FORM	C-101) FOR SUCH PROPOSALS!)			
Type of Well:	12	9131713171	Harroun 15	
WELL X WELL	OTHER		NAC-II NI-	
Name of Operator Pogo Producing Company			₅Well No.	,
Address of Operator			Pool name or Wildca	at i
P. O. Box	x 10340, Midland, TX 7	9702-7340	Pierce Cros	sing BoneSpring, E
4Well Location	0 Sauth	220		Fact
Unit Letter1 :226	9 Feet From The South	Line and330	Feet From The	East Line
Section 15	Township 24S	Range 29E	NMPM	Eddy county
Contract to the second	10Elevation (Show whether Di	Ttongo		,
医圆锥虫乳 法法律 计一生	2930' GR			
11 Check A	Appropriate Box to Indicate N	lature of Notice, Re	port, or Other I	Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
			02402.11	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING C	PNS. X	PLUG AND ANBANDONMENT
PULL OR ALTER CASING CASING TEST AND CEM			ENT JOB	
OTHER:		OTHER:		Γ
			- M	
12Describe Proposed or Completed Operation work) SEE RULE 1103.	ons (Cleany state all pertinent details, and g	ve pertinent dates, including es	stimated date of starting	any proposed
mp o p 1 .: G . D 11 6	2/421 1 / 2022 TD1-1	2 15:20 less 2/11/07   Lo	and well w/ Wes	torn Atlas Dan 190 its 1
1/2" 11 60# L-55 & N_80 I T&C	3/4" hole to 8022'. TD reached @	g 15:50 ms 2/11/97. Lo collar @ 7977'. Stage to	gged wen w/ wes	93. Howco cmt'd 1 <sup>st</sup> stage
1/2" 11.60# J-55 & N-80 LT&C csg. Float shoe @ 8022. Float collar @ 7977'. Stage tools @ 6198 & 4493. Howco cmt'd 1st stage w/ 410 sks Cl "H" + 5 pps Microbond + 2.4 pps KCl + .6% H322 @ 15.6 ppg. Drop plug. Float held. Drob bomb & open DV tool @				
6198'. Circ 5 hrs between stages. Rec 75 sks excess cmt. Cmt 2 <sup>m</sup> stage w/ 4/4 sks Cl "H" + 5 pps Microbond + 2.4 ppg KCl + .0%				
H322 @ 15.6 ppg. Drop plug. Float held. Drop bomb & open DV tool @ 4493'. Circ 5 hrs between stages. Rec 53 sks excess cmt.				
Cmt 3 <sup>rd</sup> stage w/ 640 sks Cl "H" + 5 pps Microbond + 2.4 pps KCl + .6% H322 @ 15.6 ppg. Plug down @ 00:45 hrs 02/15/97. TOC @ 2160'. ND BOP's. Set slips & make cut-off. Weld on WH & test to 2500 psi.				
@ 2100 . ND BOP s. Set snps	& make cut-on. Weld on will &	test to 2500 psi.		
·				
I hereby certify that the information above	is true and complete to the best of my know	ledge and belief		
Call	1/1:1/		ion Toch	00/24/02
SIGNATURE COLORS	my m	τπιε Sr. Operat	TOIL LECTI	DATE 09/24/03
TYPE OR PRINT NAME Cathy Wr	ight	432-6	85-8100	TELEPHONE NO.
(This space for State Use)			<del></del>	
0	ra tq			
1/ /	٠٠٠ - ٢٠٠٠			DATE 10-15-03