

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON
Governor
Betty Rivera
Cabinet Secretary



Lori Wrotenbery
Director
Oil Conservation Division

Yates Petroleum Corporation 105 South 4th Street Artesia, New Mexico 88210

Form C-103 Report of Plugging for your Han lad AKZ St. #3-Sec 13-T8S-R27E-30-005-63073 Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

	1	All	pits	have	been	filled	and	level	ed
--	----------	-----	------	------	------	--------	-----	-------	----

2. Rat hole and cellar have been filled and leveled.

3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)

4. The location has been leveled as nearly as possible to original top ground contour and has been deared of all junk and equipment.

5. The dead men and tie downs have been cut and removed.

6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.

7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

Dela Syro

Submit 3 Copies To Appropriate District Office State of New Mexico Office State of New Mexico								
Submit 3 Copies To Appropriate District Office District Figure 1 State of New Mexico Energy Minerals and Natural Reso	Form C-103							
District! Energy symmetrals and Natural Reso	well API NO.							
District II District III Dis	ION 30-005-63073							
1000 Dis Dans Del Anti- Color of Color	5. Indicate Type of Lease STATE XX FEE							
District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.							
1220 S. St. Francis Dr., Santa RAM 87505	VB-0427							
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DEEPEN OF PLUG BACK TO DEEPEN DE	!							
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Hanlad AKZ State 8. Well Number							
1. Type of Well: Oil Well Gas Well Other Plug & Abandon	3							
2. Name of Operator	9. OGRID Number							
Yates Petroleum Corporation	025575							
3. Address of Operator 105 South Fourth Street - Artesia, NM 88210	10. Pool name or Wildcat Acme San Andres, Southeast							
4. Well Location								
Unit Letter L : 2310 feet from the South lin	e and 330 feet from the West line							
Section 13 Township 8S Range 27								
11. Elevation (Show whether DR, RKB, RT 3949 GR	T, GR, etc.)							
12. Check Appropriate Box to Indicate Nature of	Notice, Report or Other Data							
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:							
PERFORM REMEDIAL WORK PLUG AND ABANDON REMED	DIAL WORK ALTERING CASING							
TEMPORARILY ABANDON	ENCE DRILLING OPNS. PLUG AND ABANDONMENT							
PULL OR ALTER CASING MULTIPLE CASING COMPLETION CEMEN	TEST AND IT JOB							
OTHER: OTHER	:: 🗆							
13. Describe proposed or completed operations. (Clearly state all pertinent of the complete of								
of starting any proposed work). SEE RULE 1103. For Multiple Completion.	etions: Attach wellbore diagram of proposed completion							
7-16-2003 - Moved in pulling unit and plugging equipment. Spotted equipment.								
7-17-2003 - Moved pumping unit off hole. Rigged up pulling unit. Jarred on pump for 2 hours. POOH with rods. Left cups with standing valve in hole. Rigged down rod								
equipment. Nippled down wellhead and nippled up BOP. Rigged up floor and tubing								
equipment. Shut well in for night.	Chut wall in Dia wannin							
7-18-2003 - POOH with tubing. RIH with 10 joints 7-19-22-2003 - RIH to 2200'. Circulated hole with the control of the control								
Class C Neat cement. POOH with 50 joints. Shut	well in for night. WOC.							
7-23-2003 - RIH with tubing and tagged plug at 19 mud. Pulled up hole to 535. Circulated 55 sac								
surface. POOH with tubing and rigged down tubing equipment and floor. Nippled down								
BOP. Topped off cement. Rigged down pulling unit and plugging equipment. Installed								
regulation abandonment marker. <u>PLUGGED AND ABANDONED - FINAL REPORT.</u> Plugging completed 7-22-2003.								
_	1/2							
Thereby certify that the information above is true and complete to the best of my	knowledge and belief.							
J f v v v v	ORY COMPLIANCE TECH DATE 7-31-03							
Type or print name DONNA CLACK E-mail address:	Telephone No505-748-1471							
(This space for State use)								
APPPROVED BY TITLE DATE Conditions of approval, if any:								
Conditions of approval, a any.	APPROVED OCT 1 5 2003							