Form 3160-5 (February 2005)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD-ARTESIA

FORM APROVED OMB NO. 1004-0135 EXPIRES: March 31, 2007 5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS

NM 81953

Do not use this form for proposals to drill or to re-enter an				NM 81953 6. If Indian, Allottee or Tribe Name	
abandoned well. Use Form 3160-3 (APD) for such proposals  SUBMIT IN TRIPLICATE			<i></i>	o. Il ilidian, Allottee or	Tibe Name
SUBMIT IN TRIPLICATE				7. Unit or CA Agreement Name and No.	
1a. Type of Well Oil Well Gas \	Well Other	NOV 2 6 20	ንበ7	8 Well Name and No.	
D. N					
2. Name of Operator  DEVON ENERGY PRODUCTION COMPANY, LP  OCD-ARTESIA				North Pure Gold 4 Federal 3  9. API Well No.	
Address and Telephone No.				1 -	015-35702
20 N. Broadway, Oklahoma City, Ok 73102-8260 405-235-3611				10. Field and Pool, or	
Location of Well (Report location clearly and in accordance with Federal requirements)*				· ·	anos; Delaware
180' FNL 660' FWL Unit D SEC 4 T23S R31E				11. County or Parish State	
				NM	
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA					
TYPE OS SUBMISSION TYPE OF ACTION					
☐ Notice of Intent	Acidize	Deepen		n (Start/Resume)	Water Shut-Off
	Alter Casing	<u> </u>			
✓ Subsequent Report		New Construction Plug and Abandon	Recomple	Completion	
I I FINAL ANADOONMENT NOTICE		Plug Back	Water Dis	•	Report
interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection)  9/21/07 - 11/04/07 NU BOP. TOC @ 4554'. DV Tool @ 4562'. PBTD @ 8141'. CHC w/ 2% KCL wtr. Run GR/CCL & perf L. Brushy Canyon 7925-40'. RU Schlumberger WL ran Gauge ring & junk basket on Gamma tool. RD WL. RU BJ test to 7000#. BD perfs. Pump 1000 gals 7 1/2% acid, flush w/ 220 gals Technihib 756. Frac L. Brushy Canyon 8025-40' w/ 32K gals Spectra Star 2500 Gel, 1K# 100 Mesh sd, 38K# 20/40 sd and 18K# 16/30, flush w/ gel. RD BJ. RU Schlumberger WL run 4" cased perf gun perf L. Brushy Canyon 7815-30' @ 2 spf: 30 holes. RD WL. RU BJ & test to 7000#. Pump 1500 gals 7 1/2% acid, flush 220 gals Technihib 756 & frac L. Brushy Canyon 7815-30' w/ 49K gals Spectra Star 2500 gel, 1500# 100 Mesh sd, 65K# 20/40 white sd & 20K# 16/30 Siberprop sd. Flush w/ Gel. ND BOP. NU WH. RIH w/ pump & produce to frac tanks. RDMO PU. Battery complete & start producing. POP.  14. Thereby certify that the foregoing is true and correct					
Signed and Barn	Name Title	Judy A. Barnett >		Date	11/14/2007
(This space for Federal or State Office used	NEOCOD I			<u> </u>	
(This space for Federal of State Office use)	RECORD				
Approved by Conditions of approved, it and	R CIACE			Date	
	107				
Title 18 0 S.C. Section 1001, makes it a criffie for any pe		y department or agency or the ornite within its jurisdiction	u States any laist	a, notinous or fraudulent staten	nents of representations to any matter
			= <u></u>		
DAVID R. GLA PETROLEUM ENG	SS	Instruction on Reverse Si	ue		