Office		ew Mexico	Form C-103
District I	Energy, Minerals ar	nd Natural Resources	WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II	OF COMOTRIE	TION DIVISION	30-015-35342
1301 W. Grand Ave., Artesia, NM 88210		ATION DIVISION	5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410		St. Francis Dr.	STATE FEE
District IV	Santa Fe,	NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name Winchester 5 State
	Gas Well 🛛 Other		8. Well Number 1
2. Name of Operator	esources, LLC	NOV 15 2007	9. OGRID Number 217955
3. Address of Operator	64 Midland, TX 79702	OCD-ARTESIA	10. Pool name or Wildcat Salt Draw Morrow, West
4. Well Location			
Unit Letter_KSection s5 Towns	:1980feet from the _S ship 25S Range 28E		
	11. Elevation (Show whet		
Pit or Below-grade Tank Application □ or			
Pit type Depth to Groundwa		st fresh water well I	Distance from nearest surface water
Pit Liner Thickness: mil	Below-Grade Tank: Volum		Construction Material
12. Check A	appropriate Box to mui	cate mature of motic	e, Report or Other Data
NOTICE OF IN	TENTION TO:	SU	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	·	REMEDIAL WO	
TEMPORARILY ABANDON			RILLING OPNS. P AND A
	MULTIPLE COMPL	☐ CASING/CEME	NT JOB
PULL OR ALTER CASING			
OTHER:		OTHER:	
OTHER: 13. Describe proposed or complete of starting any proposed work.		tate all pertinent details,	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or compl		tate all pertinent details,	
OTHER: 13. Describe proposed or complete of starting any proposed work.	rk). SEE RULE 1103. For	tate all pertinent details, Multiple Completions:	Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or completion of starting any proposed work or recompletion.	rk). SEE RULE 1103. For ar off mill. Mill window in	tate all pertinent details, Multiple Completions:	Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 10-10-2007 Set whipstock and sheat 10-11-07 to 11-8-07 Drill, survey & 11-9-07 RIH with shoe, 1 jt 4 ½" 1 stds. DP. Set liner @ 12,8	rk). SEE RULE 1103. For ar off mill. Mill window in slide. 1.60# P-110 csg., float colla	tate all pertinent details, and Multiple Completions: 7" casing from 9374' to har, landing collar, 93 jts 4	Attach wellbore diagram of proposed completion 9385'. 1/2" csg. & liner hanger. TIH with liner & 94
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 10-10-2007 Set whipstock and sheat 10-11-07 to 11-8-07 Drill, survey & 11-9-07 RIH with shoe, 1 jt 4 ½" 1 stds. DP. Set liner @ 12,8 cemented w/ 300 sks Super	rk). SEE RULE 1103. For ar off mill. Mill window in slide. 1.60# P-110 csg., float colla 333'. r H cement + .05% Halad-F	tate all pertinent details, and Multiple Completions: 7" casing from 9374' to har, landing collar, 93 jts 4 R + 0.4% CFR-3 + 3# Gi	Attach wellbore diagram of proposed completion 9385'. 1/2" csg. & liner hanger. TIH with liner & 94 sonite + 1# Salt + 0.3% HR-7. Wt. 13.0,
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 10-10-2007 Set whipstock and sheat 10-11-07 to 11-8-07 Drill, survey & 11-9-07 RIH with shoe, 1 jt 4 ½" 1 stds. DP. Set liner @ 12,8 cemented w/ 300 sks Super	rk). SEE RULE 1103. For ar off mill. Mill window in slide. 1.60# P-110 csg., float colla 333'. r H cement + .05% Halad-F	tate all pertinent details, and Multiple Completions: 7" casing from 9374' to har, landing collar, 93 jts 4 R + 0.4% CFR-3 + 3# Gi	Attach wellbore diagram of proposed completion 9385'. 1/2" csg. & liner hanger. TIH with liner & 94
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 10-10-2007 Set whipstock and sheat 10-11-07 to 11-8-07 Drill, survey & 11-9-07 RIH with shoe, 1 jt 4 ½" 1 stds. DP. Set liner @ 12,8 cemented w/ 300 sks Super	rk). SEE RULE 1103. For ar off mill. Mill window in slide. 1.60# P-110 csg., float colla 333'. r H cement + .05% Halad-F	tate all pertinent details, and Multiple Completions: 7" casing from 9374' to har, landing collar, 93 jts 4 R + 0.4% CFR-3 + 3# Gi	Attach wellbore diagram of proposed completion 9385'. 1/2" csg. & liner hanger. TIH with liner & 94 sonite + 1# Salt + 0.3% HR-7. Wt. 13.0,
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 10-10-2007 Set whipstock and sheat 10-11-07 to 11-8-07 Drill, survey & 11-9-07 RIH with shoe, 1 jt 4 ½" 1 stds. DP. Set liner @ 12,8 cemented w/ 300 sks Super	rk). SEE RULE 1103. For ar off mill. Mill window in slide. 1.60# P-110 csg., float colla 333'. r H cement + .05% Halad-F	tate all pertinent details, and Multiple Completions: 7" casing from 9374' to har, landing collar, 93 jts 4 R + 0.4% CFR-3 + 3# Gi	Attach wellbore diagram of proposed completion 9385'. 1/2" csg. & liner hanger. TIH with liner & 94 sonite + 1# Salt + 0.3% HR-7. Wt. 13.0,
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 10-10-2007 Set whipstock and sheat 10-11-07 to 11-8-07 Drill, survey & 11-9-07 RIH with shoe, 1 jt 4 ½" 1 stds. DP. Set liner @ 12,8 cemented w/ 300 sks Super	rk). SEE RULE 1103. For ar off mill. Mill window in slide. 1.60# P-110 csg., float colla 333'. r H cement + .05% Halad-F	tate all pertinent details, and Multiple Completions: 7" casing from 9374' to har, landing collar, 93 jts 4 R + 0.4% CFR-3 + 3# Gi	Attach wellbore diagram of proposed completion 9385'. 1/2" csg. & liner hanger. TIH with liner & 94 sonite + 1# Salt + 0.3% HR-7. Wt. 13.0,
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 10-10-2007 Set whipstock and sheat 10-11-07 to 11-8-07 Drill, survey & 11-9-07 RIH with shoe, 1 jt 4 ½" 1 stds. DP. Set liner @ 12,8 cemented w/ 300 sks Super	rk). SEE RULE 1103. For ar off mill. Mill window in slide. 1.60# P-110 csg., float colla 333'. r H cement + .05% Halad-F	tate all pertinent details, and Multiple Completions: 7" casing from 9374' to har, landing collar, 93 jts 4 R + 0.4% CFR-3 + 3# Gi	Attach wellbore diagram of proposed completion 9385'. 1/2" csg. & liner hanger. TIH with liner & 94 sonite + 1# Salt + 0.3% HR-7. Wt. 13.0,
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 10-10-2007 Set whipstock and sheat 10-11-07 to 11-8-07 Drill, survey & 11-9-07 RIH with shoe, 1 jt 4 ½" 1 stds. DP. Set liner @ 12,8 cemented w/ 300 sks Super	rk). SEE RULE 1103. For ar off mill. Mill window in slide. 1.60# P-110 csg., float colla 333'. r H cement + .05% Halad-F	tate all pertinent details, and Multiple Completions: 7" casing from 9374' to har, landing collar, 93 jts 4 R + 0.4% CFR-3 + 3# Gi	Attach wellbore diagram of proposed completion 9385'. 1/2" csg. & liner hanger. TIH with liner & 94 sonite + 1# Salt + 0.3% HR-7. Wt. 13.0,
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 10-10-2007 Set whipstock and sheat 10-11-07 to 11-8-07 Drill, survey & 11-9-07 RIH with shoe, 1 jt 4 ½" 1 stds. DP. Set liner @ 12,8 comented w/ 300 sks Superyield 1.68, slurry 90 bbls, of the starting of the sta	rk). SEE RULE 1103. For ar off mill. Mill window in & slide. 1.60# P-110 csg., float colla 333'. r H cement + .05% Halad-F diaplace with 58 bbls water	tate all pertinent details, and Multiple Completions: 7" casing from 9374' to ar, landing collar, 93 jts 48 + 0.4% CFR-3 + 3# Gi + 67 bbls mud, total diagon to the best of my knowled.	Attach wellbore diagram of proposed completion 9385'. 1/2" csg. & liner hanger. TIH with liner & 94 sonite + 1# Salt + 0.3% HR-7. Wt. 13.0, placement 125 bbls. Did not bump plug.
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 10-10-2007 Set whipstock and sheat 10-11-07 to 11-8-07 Drill, survey & 11-9-07 RIH with shoe, 1 jt 4 ½" 1 stds. DP. Set liner @ 12,8 comented w/ 300 sks Superyield 1.68, slurry 90 bbls, of the starting of the sta	rk). SEE RULE 1103. For ar off mill. Mill window in & slide. 1.60# P-110 csg., float colla 333'. r H cement + .05% Halad-F diaplace with 58 bbls water	tate all pertinent details, and Multiple Completions: 7" casing from 9374' to ar, landing collar, 93 jts 48 + 0.4% CFR-3 + 3# Gi + 67 bbls mud, total diagon to the best of my knowled.	Attach wellbore diagram of proposed completion 9385'. 1/2" csg. & liner hanger. TIH with liner & 94 sonite + 1# Salt + 0.3% HR-7. Wt. 13.0, placement 125 bbls. Did not bump plug.
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 10-10-2007 Set whipstock and sheat 10-11-07 to 11-8-07 Drill, survey & 11-9-07 RIH with shoe, 1 jt 4 ½" 1 stds. DP. Set liner @ 12,8 cemented w/ 300 sks Superyield 1.68, slurry 90 bbls, of the starting of the sta	ar off mill. Mill window in slide. 1.60# P-110 csg., float collagas. The cement + .05% Halad-Fediaplace with 58 bbls water slowers is true and complete telepsed according to NMOCD gni	tate all pertinent details, Multiple Completions: 7" casing from 9374' to ar, landing collar, 93 jts 4 R + 0.4% CFR-3 + 3# Gi + 67 bbls mud, total diagonal collar, 93 jts 4 o the best of my knowled delines , a general permit	Attach wellbore diagram of proposed completion 9385'. 1/2" csg. & liner hanger. TIH with liner & 94 sonite + 1# Salt + 0.3% HR-7. Wt. 13.0, placement 125 bbls. Did not bump plug.
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 10-10-2007 Set whipstock and sheat 10-11-07 to 11-8-07 Drill, survey & 11-9-07 RIH with shoe, 1 jt 4 ½" 1 stds. DP. Set liner @ 12,8 ccmented w/ 300 sks Superyield 1.68, slurry 90 bbls, of SIGNATURE In Gel Angela Lightner Type or print name Angela Lightner	rk). SEE RULE 1103. For ar off mill. Mill window in & slide. 1.60# P-110 csg., float colla 333'. r H cement + .05% Halad-Fdiaplace with 58 bbls water blove is true and complete teloged according to NMOCD guine.	The Let Consultant of Le	Attach wellbore diagram of proposed completion 9385'. 1/2" csg. & liner hanger. TIH with liner & 94 sonite + 1# Salt + 0.3% HR-7. Wt. 13.0, placement 125 bbls. Did not bump plug.
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 10-10-2007 Set whipstock and sheat 10-11-07 to 11-8-07 Drill, survey & 11-9-07 RIH with shoe, 1 jt 4 ½" 1 stds. DP. Set liner @ 12,8 ccmented w/ 300 sks Superyield 1.68, slurry 90 bbls, of SIGNATURE In Gel Angela Lightner Type or print name Angela Lightner	ar off mill. Mill window in stide. 1.60# P-110 csg., float colla 333'. The cement + .05% Halad-Fediaplace with 58 bbls water diaplace with 58 bbls water. The colored according to NMOCD guides. E-mail address: angel	The Late all pertinent details, and Multiple Completions: 7" casing from 9374' to see the control of the late of my knowled delines a general permit of the Late of L	Attach wellbore diagram of proposed completion 9385'. 1/2" csg. & liner hanger. TIH with liner & 94 sonite + 1# Salt + 0.3% HR-7. Wt. 13.0, placement 125 bbls. Did not bump plug. Ige and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan . PATE11-13-2007 ephone No. 432-682-0440
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 10-10-2007 Set whipstock and sheat 10-11-07 to 11-8-07 Drill, survey & 11-9-07 RIH with shoe, 1 jt 4 ½" 1 stds. DP. Set liner @ 12,8 ccmented w/ 300 sks Superyield 1.68, slurry 90 bbls, of SIGNATURE In Gel Angela Lightner Type or print name Angela Lightner	ar off mill. Mill window in stide. 1.60# P-110 csg., float colla 333'. The cement + .05% Halad-Fediaplace with 58 bbls water diaplace with 58 bbls water. The colored according to NMOCD guides. E-mail address: angel	The Let Consultant of Le	Attach wellbore diagram of proposed completion 9385'. 1/2" csg. & liner hanger. TIH with liner & 94 sonite + 1# Salt + 0.3% HR-7. Wt. 13.0, placement 125 bbls. Did not bump plug. Ige and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan . PATE11-13-2007 ephone No. 432-682-0440