## FFB 12 2008 OCD-ARTESIA Submit 2 Copies To Appropriate District State of New Mexico Form C-103 Office October 25, 2007 Energy, Minerals and Natural Resources District I WELL API NO 1625 N. French Dr., Hobbs, NM 8824 30 - 0/5 - 2003/ 5. Indicate Type of Lease District II OIL CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, NM 88210 1220 South St. Francis Dr. District III STATE | FEE 🔀 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District IV 1220 S St Francis Dr., Santa Fe, NM SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH 1. Type of Well: Oil Well Gas Well V Other PA 9. OGRID Number 2. Name of Operator Yates Petroleum Corporation 10. Pool name or Wildcat 3. Address of Operator Penasco Draw SA yeso 105 S. 4th Street, Artesia, NM 88210 4. Well Location Unit Letter (): 330 feet from the S line and 1650 feet from the E line Township 185 Range 25E NMPM County Eddy 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF 2003 NOTICE OF INTENTION TO: Gerry Guye Took of Feld Inspector PLUG AND ABANDON PERFORM REMEDIAL WORK COMMENCE DRILLING OPNS MMOCBADIStrict II ARTESIA TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB □ Location is ready for OCD inspection after P&A OTHER All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash. flow lines and other production equipment Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.) All other environmental concerns have been addressed as per OCD rules Pipelines and flow lines have been abandoned in accordance with 19 15.9.714.B(4)(b) NMAC. All fluids have been removed from non-retrieved flow lines and pipelines. When all work has been completed, return this form to the appropriate District office to schedule an inspection. If more than one inspection has to be made to a P&A location because it does not meet the criteria above, a penalty may be assessed. SIGNATURE Le R. Richards E-MAIL: Irichards experment PHONES75-748-1471

For State Use Only