Form 3160-5 (April 2004)

OCD-ARTESIA

UNITED STATES
DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

5. Lease S
NML

FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007

٠.	Lease Serial INO						
	NMLC028731B						

SUNDRY	NOTICES AND REI	PURIS UN WEI	Tro			
Do not use the abandoned we	nis form for proposals t ell. Use Form 3160 - 3 (to drill or to re-e APD) for such pro	nter an posals.	6 If Indian, A	Allottee or Tribe Name	
SUBMIT IN TRIPLICATE- Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No. NMNM111789X	
1 Type of Well Gas Well Other MAR 2 5 2008			8. Well Name and No.			
		OCD-ARTESIA			Dodd Federal Unit #23 WIW 9. API Well No.	
3a. Address PO Box 227, Artesia, NM 88211-0227		3b. Phone No. (include area code) 575-748-3303		30-015-25790		
4. Location of Well (Footage, Sec., T, R, M, or Survey Description)		3,0 , 10 0000		10. Field and Pool, or Exploratory Area Grbg Jackson SR Q Grbg SA		
25 FWL 125 FNL, Sec. 14-T17				11. County or Parish, State		
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, R				Eddy Co., NM REPORT, OR OTHER DATA		
	PPROPRIATE BOX(ES) TO			EPORT, OR C	JIHEK DATA	
TYPE OF SUBMISSION		171	PE OF ACTION			
Notice of Intent	Acidize	Deepen	Production (St	art/Resume) L	Water Shut-Off	
-	Alter Casing	Fracture Treat	Reclamation	L T	Well Integrity	
Subsequent Report	Casing Repair Change Plans	New Construction	Recomplete Temporarily A	L	Other	
Final Abandonment Notice	Convert to Injection	Plug and Abandon Plug Back	Water Disposal	Dandon		
determined that the site is ready Converted to WIW as foll 1/30/08 - POOH w/ rods & 1/31/08 - RIH w/ csg scrap w/ pkr. Set cmt rtnr @ 2' 2/1/08 - Re-sqz perfs w/ 30 2/2/08 - Drill out sqz to 29 POOH w/ tbg & DC's. 2/5/08 - Set cmt rtnr @ 2' 3000# & hold. Reverse out 2/6/08 - Drill out cmt & ri 2/7/08 - Cont drlg cmt f/ 3 2/8/08 - RIH w/ 5 1/2" x 2	lows: & pump. NU BOP. POOH & per to 4343'. POOH w/ scrape 725'. Sqz perfs @ 2789' - 3405 00 sx Class C cmt. Sqz to 3500 31'. Fell out to 2941'. Lost all 749'. Press up annulus to 500# at. POOH w/ stinger. thr f/ 2740' - 3046'. 3046'. 3405'. Test sqz to 600#, 3/8" R-4 pkr & 130 jts 2 7/8" of or 30 min, OK. Richard Ing	lay down production ther. RIH w/ CIBP & pkr 'w/ 400 sx Class C cmt 0#. Unsting f/ rtnr. Rev returns. Cont rotating & hold. Est injection r OK. Drill out CIBP @ 1PC tbg to 4136'. Loac	og Set CIBP @ 3500' erse out. in hole to 3466'. Hit ate to 1100# @ 2 BF	Set pkr @ 3490 an occasional b M. Re-sqz perf	o'. Test CIBP to 2000#. POOH oridge. Clean out below perfs. s w/ 400 sx Class C cmt. Sqz to k lay down work string.	
14. Thereby certify that the fore Name (Printed/Typed)	egoing is true and correct					
Diana J. Briggs	()	Title P	roduction Analyst			
Signature	Suran	Date		03/10/2948CC	EPTED FOR RECORD	
	THIS SPACE FOR	FEDERAL OR S	TATE OFFICE	USE		
	V 3				MAD 2 2 2000	
Approved by			itle	Da	e MAR 2 2 2008	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.				PR	Umo	
Title 18 U.S.C. Section 1001 and Tit		a crime for any person ki s as to any matter within it	nowingly and willfully s jurisdiction.	to make to any	REAU OF LAND MANAGEMENT DEPTENDENT OF THE	

