#### Form 3160-5 (August 2007)

## OCD-ARTESIA

### UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

MAY - 9 2008

FORM APPROVED OMB No 1004-0137 Expires July 31, 2010

OCD-ARTESPANIANO

Reclamation

Recomplete

NM070603

6 If Indian. Allottee or Tribe Name

SUNDRY NUTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an

Alter Casing

Casing Repair

Change Plans

abandoned well. Use Form 3160-3 (APD) for such proposals. 7 If Unit of CA/Agreement, Name and/or No SUBMIT IN TRIPLICATE - Other instructions on page 2 1 Type of Well 8 Well Name and No Oil Well Gas Well Other Shearn Samantha Federal #1 2 Name of Operator C&D MANAGEMENT COMPANY/dba Freedom Ventures 9 API Well No OGRID: 231382 30-015-31059 3a Address 3b Phone No (include area code) 10 Field and Pool or Exploratory Area 4801 Lang NE Suite 110 Alburquerque, New Mexico 87109 Emprire Yates 7 Rivers 814-688-3297 - 505-417-1511 Location of Well (Footage Sec T R M, or Survey Description) 1649' FNL & 1523' FEL [Unit G] 11 Country or Parish. State Section 14-T17S-R27F 12 CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Deepen Water Shut-Off Production (Start/Resume) ✓ Notice of Intent

Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13 Describe Proposed or Completed Operation Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA Required subsequent reports must be filed within 30 days following completion of the involved operations If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has

Fracture Treat

New Construction

✓ Plug and Abandon

We are proposing to Plug & Abandon the above well by placing a plug at botton of the hole of 25 sack Class C cement then placing a plug at top of 25 sacks Class C cement. Total depth of well is 650 feet. And then set Abandoment Marker.

This well is under bond #NMB002455

determined that the site is ready for final inspection )

Subsequent Report

(Instructions on page 2)

Accepted for record

Well Integrity

# SEE ATTACHED FOR CONDITIONS OF APPROVAL

14 I hereby certify that the foregoing is true and correct Name (Printed/Typed) Thomas Kizer	Title President			
Signature	Date 04/08/2008		AL ENAVIEW	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE		APPROVED		
Approved by	Title	Date	MAY 8	8 2008
Conditions of approval, if any, are attached. Approval of this notice does not warrant or ce that the applicant holds legal or equitable title to those rights in the subject lease which wo entitle the applicant to conduct operations thereon			MINA WESLEYW	INGRAM
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any per ficultious or fraudulent statements of representations as to any matter within its prosdetion		tment or	RETROPHENMO	esnging are

# Shearn Samantha Federal #1 C&D Management Company May 8, 2008 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to start.

- 1. Well is to be plugged from TD to surface with Class C neat cement using tubing. Tag TD with tubing and record depth.
- 2. When casing is cut off verify that cement is in annuli of all casing strings. If not, it will be necessary to one inch cement from a minimum of 60' below surface to surface.
- 3. See standard COA for plug and abandonment that is attached.

WWI 050808

Accepted for record NMOCD

# BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

### Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

- 6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.

Accepted for record NMOCD