Form 3160-5 (August 2007)

### **OCD-ARTESIA**

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

abandoned well. Use Form 3160-3 (APD) for such proposals.

FORM APPROVED OMB No 1004-0137 Expires July 31, 2010

itsease Serial No

NM070603

6 If Indian, Allottee or Tribe Name

MAY - 9 2008

### OCD-ARTESIA

SUBMIT IN TRIPLICATE – Other instructions on page 2				7 If Unit of CA/Agreement, Name and/or No 35256		
1 Type of Well						
Oil Well Gas Well Other				8 Well Name and No Shearn Becky Federal #1		
2 Name of Operator C&D MANAGEMENT COMPANY/dba Freedom Ventures OGRID 231382				9 API Well No 30-015-34470 34440		
3a Address 4801 Lang NE, Suite 110 Alburquerqu	3b Phone No <i>(include area coa</i> 814-688-3297 - 505-417-18	,	10 Field and Pool or Exploratory Area Emprire Yates 7 Rivers			
4 Location of Well (Footage Sec. T. R. M. or Survey Description) 660' FNL & 1650' FEL [Unit B, NENE]]				11 Country or Parish. State Section 14-T17S-R27E		
12 CHEC	K THE APPROPRIATE B	OX(ES) TO INDICATE NATURE	OF NOTIO	CE. REPORT OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF /			TION		
✓ Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	=	duction (Start/Resume)	Water Shut-Off Well Integrity	
Subsequent Report	Casing Repair	New Construction	=	omplete	Other	
Final Abandonment Notice	Change Plans Convert to Injection	✓ Plug and Abandon ☐ Plug Back		porarily Abandon er Disposal		
	ally or recomplete horizonta work will be performed or p ed operations. If the opera Abandonment Notices mus r final inspection.)	ally, give subsurface locations and a roule the Bond No on file with B tion results in a multiple completion	measured and LM/BIA For or recomplishing the second of the	and true vertical depths of Required subsequent repo pletion in a new interval, a g reclamation, have been c	all pertinent markers and zones, orts must be filed within 30 days a Form 3160-4 must be filed once completed and the operator has	If
This well is under bond #NMB(	002455					

# SEE ATTACHED FOR CONDITIONS OF APPROVAL

	Accepted for record NMOCD
14 Thereby certify that the foregoing is true and correct. Name (Printed/Typed) Thomas Kizer  Trite	President
Signature	04/08/2008
THIS SPACE FOR FEDERAL	OR STATE OFFICE USE APPROVED
Approved by  Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would	Title DatMAY 8 2009 Office
entitle the applicant to conduct operations thereon  Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person fictinous or fraudulent statements or representations as to any matter within its jurisdiction	wester willfully to make to an depart per receive Mile North any false any false

### Shearn Becky Federal #1 C&D Management Company May 8, 2008 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to start.

- 1. Well is to be plugged from TD to surface with Class C neat cement using tubing. Tag TD with tubing and record depth.
- 2. When casing is cut off verify that cement is in annuli of all casing strings. If not, it will be necessary to one inch cement from a minimum of 60' below surface to surface.
- 3. See standard COA for plug and abandonment that is attached.

WWI 050808

Accepted for record NMOCD

### BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

#### Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

- 6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged.</u>
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.

Accepted for record NMOCD