UNITED STATES February 2005 DEPARTMENT OF THE INTERIOR

OCD-ARTESIA

FORM APROVED

BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS

abandoned well. Use Form 3160-3 (APD) for such proposals

Do not use this form for proposals to drill or to re-enter an

OMB NO. 1004-0135 EXPIRES: March 31, 2007

5. Lease Serial No.

NM 89051 6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE				7 Unit or CA Acre	sement Name and No
1a. Type of Well Oil Well Gas Well Other				7. Unit or CA Agreement Name and No.	
				8 Well Name and No.	
2. Name of Operator DEVON ENERGY PRODUCT	MAY 28 2008		Apache 13 Federal 1 9. API Well No.		
3. Address and Telephone No.		OCD-ARTESIA		30-015-27434	
20 North Broadway, Oklahoma City, OK 73102		405-235-3611		10. Field and Pool, or Exploratory	
4. Location of Well (Report location clearly and in accordance with Federal requirements)*				Los Medanos;Wolfcamp	
1330' FNL 330' FEL SEC 13	·		11. County or Parish State		
				Eddy	NM
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OS SUBMISSION TYPE OF ACTION					
TIFE OS SOBIVILOSION				- (Ch. +/D)	DWater Chat Off
✓ Notice of Intent	Acidize Alter Casing	☐ Deepen☐ Fracture Treat	Reclamati	n (Start/Resume)	
Subsequent Report	Casing Repair	New Construction	Recomple		Other
Final Abandonment Notice	Change Plans	Plug and Abandon		ily Abandon	
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work and approximate duration thereof. If the proposal deepen directionally or recomplete horizontally, give subsurface location and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)					
Devon Energy respectfully requests to return well to production in the Wolfcamp. Recompletion to the Strawn unsuccessful. 1. MIRU WSU. LT & backside w/ 2% KCL wtr. ND tree. NU BOPE & test. 2. Unset production pkr @ 12,333' & POOH w/ tbg & BHA. 3. RU WLSU & WL BOPE. Test. RIH w/ CIBP on WL & set @ 12,400'. 4. RIH w/ original BHA (WL re-entry guide, 1.891" R-profile nipple, 10' pup jt, 4 1/2" retrv production pkr & on-off tool w/ 1.81" F-profile on 2 3/8" tbg) to 11,850' EOT. Circ w/ 2% KCL w/ corrosion inhibitor. ND BOP. Hang tbg & NU production tree & test. RD well service unt. 5. Swab well in and flow well back. test to tank until well cleans up & stable rate is achieved. Turn to sales.					
Signed Judy	Arnee Nam			Date	4/16/2008
(This space for Federal or State Office us	e)				
Approved by Conditions of approval, if any:	Title			Date	
Title 16 0 3 C Section 1001, makes it a crime for any person knowingly and william to make any department or agency or the Onlied States any raise, inclinious or maddlefit statements or representations to any matter within its jurisdiction					

*See Instruction on Reverse Side

Accepted for record - NMOCD

APPROVED

MAY 2 4 2008

JAMES A. AMOS SUPERVISOR-EPS

