Form 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD-ARTES

FORM APPROVED

6. If Indian, Allottee or Tribe Name

OMB NO. 1004-0137 Expires March 31, 2007

,	Lease	Serial	No.

NM 012898

SUNDRY	NOTICES	AND	REPORTS	ON	WELLS
o not use this form for proposals to drill or to re-enter an					

abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side					7. If Unit or CA/Agreement, Name and/or No	
Type of Well Oil Well X Gas Well Other Name of Operator KERSEY & COMPANY A Address P.O. Box 1248, Fredericksburg, TX Location of Well (Footage, Sec., T., R., M., or Survey I) 660' FNL 660' FWL SEC. 11 T 17	JUL 10 2008 OCDARTESIA 3b. Phone No. (include area code)		8. Well Name and No. ASU #2 9. API Well No. 30-015-10227 10. Field and Pool, or Exploratory Area Vandagriff Keyes QN 11. County or Parish, State Eddy County NM			
12. CHECK APPROPRIATE	BOX(ES) TO IND	ICATE NATURE OF I	NOTICE, REP			
TYPE OF SUBMISSION	TYI	PE OF ACTION				
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction X Plug and Abandon Plug Back	Recomplet	ly Abandon	Water Shut-Off Well Integrity Other	

13 Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

4-23-08 Move In & Rig up. Set C.I.B.P @1,480'. Cap w/25 sx. cmt.

4-24-08 Perf. @900'. Sqz. 40 sx. W.O.C. & tag @775'. Perf. @470'. Sqz. 75 sx. W.O.C. & tag @230'.

4-25-08 Perf. @210'. Sqz. 50 sx. W.O.C. & tag @155'.

4-28-08 Perf. @60'. Sqz. 25 sx. Try to bring it to surface. Well did not circulate. W.O.C. re-sqz. & perf. @60' - 25 sx. P.O.O.H. w/pkr. Put hose in outside of 7" pump - 30 sx. W.O.C.

4-29-08 Pump 90 sx. outside of 7" casing to surface. Pump 10 sx. inside of 7" casing to surface.

Accepted for record

14. I hereby certify that the foregoing is true and correct Name (Printed Typed) CARY ECCLESPON	Title P&	ACCEPTED FOR RECORD
Signature Sues In I	Date 5-7-08	8
THIS SPACE FOR FEDER	AL OR STATE (OFFICE USE JUL 10 2008
Approved by	Title	Dais
Conditions of approval, if any, are attached. Approval of this notice does not warra certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon.		BUREAU OF LAND MANAGEMENT ARLSBAD FIELD OFFICE
T'4. 10 H C C C. 4' - 1001 - 1 T'4. 42 H C C C. 4' - 1212 - 1 - 4'		1 1 110 11