## **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB NO 1004-0137 Expires March 31, 2007 OCD-ARTE

## 

Lease Serial No NMNM031186

630-	
400	
EA.	- 53
Take to the same	

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-outer an

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.		6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on reverse side		7. If Unit or CA/Agreement, Name and/or No. NMNM70945X
1. Type of Well  X Oil Well Gas Well Other  2 Name of Operator  BP America Production Company  3a Address  P.O. Box 1089 Eunice NM 88231  4 Location of Well (Footage, Sec, T, R, M, or Survey UL C, 990 FNL & 2310 FWL	AUG 19 2008  OCD-ARTESIA  3b. Phone No. (include area code) 575-394-1648  Description)	8. Well Name and No.  Empire Abo Unit 6  "M"  9. API Well No.  30-015-00838  10. Field and Pool, or Exploratory Area  Empire Abo
Section 9, T18S, R27E		11. County or Parish, State  Eddy NM
12. CHECK APPROPRIATE	BOX(ES) TO INDICATE NATURE OF NOTICE, RE	EPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	N
Notice of Intent  X Subsequent Report  Final Abandonment Notice	Alter Casing Fracture Treat Reclam Casing Repair New Construction Recom Change Plans Plug and Abandon Tempo	
7/23/08: TEST WELL HEAD TO 500#. RIGUP WIRELINE AND TEST LUBURCATO TOP OF CEMENT IS AT 1370 AND RIG OF THE PLUG AT 5235. LAYDOWN THE 7/24/08: CIRC MUD AT 5223 WITH 77 OF CEMENT AT 4274. POH WITH 13 JT 7/25/08: RIH WITH 11 STANDS OF TU CEMENT, SPOT PLUG AT 3094. WAIT O 7/26/08: RIH WITH TUBING AND TAGU PLUG 25 SX. SPOT 25 SX OF CEMENT HALF PIT. RIH WITH TUBING AND TAG ALL THE TUBING AND GET READY TO W Continued on Page 2.  14. I hereby certify that the foregoing is true and correct Name (Printed Typed) Barry C. Price	RIGUP PULLING UNIT. UNLOAD TUBING FROM TRUCOR TO 500#. RIH WITH RADIAL BORD/ GR/ CCL TO EDOWN WIRELINE. PICKUP 168 JTS AND 10' OF JT 167TH JOINT AND SHUT DOWN FOR NIGHT BELS OF 9.0 PPG AT 40 VIS. POH WITH 31 JTS AND 11 STANDS OF TUBING WOC. (TUBING AT 30 BING AND TAG AT 4274 POH. POH WITH TUBING TO CEMENT TO SET UP TO TAG PP AT 2624 CALL BLM AND TOLD THEM. POH WITH AT 1726. POH WITH 13 JTS AND 11 STANDS. WALS CEMENT AT 1426 BLM SAID IT GOOD POH. POH WITH	CK. NU BOP AND RIG FLOOR  0 2500' AND LOG UP TO 500'  1 167 TUBING AND RIH TAG TOP  5 OF TUBING. PUMP 25 SX  8186) SHUT WELL IN FOR NIGHT  10 3094 AND SPOT PLUG  TUBING TO 1726 AND SPOT  TO ON CEMENT AND CLEAN
THIS	SPACE FOR FEDERAL OR STATE OFFICE USE	AUG 15 2008
Approved by	Title	Date
Conditions of approval, if any, are attached. Approval of certify that the applicant holds legal or equitable title to which would entitle the applicant to conduct operations the	4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	EXU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and will fully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Form 3160-5 Empire Abo Unit M-6 30-015-00838 Continued from Page 1

7/27/08: RIH AND TAG CEMENT AT 1360 PULL UP HOLE AND PERF CASING AT 1340 POH AND RIG DOWN WIRE LINE

PUMP 60 BBLS OF WATER DOWN 4.5 AND OUT THE 8 5/8

NIPPLE DOWN BOP AND NIPPLE UP WELL HEAD AND GET READY TO PUMP CEMENT

PUMP 350 SACKS OF CEMENT. POP A HOLE IN SURFACE HAD A SPILL OF LESS THEN 1 BBL. RUN OUT OF CEMENT DISPLACE HOLE WITH 6 BBLS TO GET CEMENT TO SURFACE ON 8 5/8

WAIT ON CEMENT WILL HAVE TO SPOT PLUG FROM TAG TO SURFACE

7/28/08: RIH WITH 11 JTS AND 12 FOOT TAG CEMENT AT 360' SPOT 35 SACKS OF CEMENT AND SPOT ALL THE WAY TO SURFACE. BLM WAS ON LOCATION

WAIT ON CEMENT

RIG DOWN AND CLEAN LOCATION

8/7/08: DIG OUT CELLAR & CUT OFF WH; WELD IN PLATE, 1" VALVE & DRY HOLE MARKER, DIGOUT & CUT OFF ANCHORS, COVER CELLAR & LEVEL LOC AREA