Form 3160-5 (April 2004)

TEDSTATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORMAPPROVED OM B No 1004-0137 Expires March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

5 Lease Serial No. NM-93180

6 If Indian, Allottee or Tribe Name not use this form for proposals to drill or to re-enter an

abandoned well. Use Form 3160 - 3 (APD) for such proposals.						
SUBMIT IN TRIPLICATE - Other instructions on reverse side.				7 If Unit or CA/Agreement, Name and/or No		
1 Type of Well			3 2008	8. Well Name and No FEDERAL COM 1625 #261		
z. Nameor Operator				9 API Well No		
LCX Energy, LLC. 3a Address 3b. Phone and a recording				30-015-33435		
110 North Marienfeld, Suite 200 Midland TX 79701 (432)262-4014				10 Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T, R, M, or Survey Description)				COTTONWOOD CREEK-WOLFCAMF		
SURFACE: 660 FSL AND 700 FEL, UL D, SEC 26, T16S, R25E BOTTOM HOLE LOCATION: 683 FNL AND 765 FEL, UL				11 County or Parish, State EDDY, NM		
A, SEC 26, T16S, R25E	PPROPRIATE BOX(ES)	ro indicate natui	RE OF NOTICE, RE	PORT, OR OTHER DATA		
TYPEOF SUBMISSION			PEOF ACTION			
Notice of Intent	Acidize AlterCasing	Deepen FractureTreat	Production (Start	Well Integrity		
Subsequent Report	Casing Repair Change Plans	New Construction X Plugand Abandon	Recomplete Temporarily Aban	Other		
X Final Abandonment-Notice	Convert to Injection	PlugBack	Water Disposal	idon .		
drill collars & RIH w/bit of Head. POOH w/tbg & D scrapper & Bit. M/U CIE CIBP on setting Tool". M 14.8 ppg and spot cmt F L/D tbg to 4100'. Mix an POOH to 1950'. Mix an w/tbg to Derrick. Shut w	N/D Tree, N/U BOP, collars and 2 3/8" tbg to collars and 2 3/8" tbg to collars, L/D D.C. BP & RIH to 6480'. Tree M/U 4 1/2" CIBP on 2 6/6480' to 6340'. POC and pump 25 sx plug F/2 pump 25 sx plug F/2 cell in and shut down for collars.	to tag Cmt @ 4850' M/U 3 7/8" bit on 4 ied to set CIBP. Cl 3/8" tbg & RIH to 6 DH w/14 jts. L/D sar 1/4100' to 3960'. PO for day.	'. Drill out cmt & C 1/2" csg scrapper IBP didn't set. PO 480' & Set CIBP @ me to racks, Reve DOH & L/D 14 jts t OH w/14 jts tbg, re	tubing. M/U 3 7/8" bit on 4 - 3 1/8" CIBP @ 4900'. R/D swivel & stripper & RIH to 6490'. POOH w/tbg., OH w/tbg and Setting Tool "NO @ 6480'. Mix & pump 25 sx cmt @ rse hole clean w/9.5# mud. POOH & rbg, Reverse tbg clean w/9.5# mud. POOH		
Note : Jim Amos w/the E	BLM said it was ok to A(0000	circulate fluids into	ACCEPTED TOR'RECOR		
14 I hereby certify that the foreg Name (Printed/Typed)	going is true and correct	SEP 4 - 2008		AUU 2 3 2300		
Jenifer Sorley	Ge	rry Guye, DeputytEield	Manetion Analys	- Como		
Signature	NM C	OCD-District II A	ARTESIA 03/25/2008	BUREAU OF LAND MANAGEMENT		
Jany	THIS SPACE FOR	<u> </u>		CARLSBAD FIELD OFFICE		
	THIS OF ACE TOR	PEDEIVAL ON O	TATE OFFICE O			
Approved by	;	<u>Tı</u>	tle	Date		
Conditions of approval, if any, are certify that the applicant holds lega which would entitle the applicant	I or equitable title to those righ	its in the subject lease of	ffice			
Title 18 U.S.C. Section 1001 and Tit States any false, fictitious or fraud	le 43 U.S.C. Section 1212, mak ulent statements or representa	te it a crime for any person kations as to any matter wit	nowingly and willfully to a	make to any department or agency of the United		