

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

NMOC

FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 2000

RECEIVED

OCT 8 1 2003

OCD-ARTESIA

SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

OCT 8 1 2003

SUBMIT IN TRIPLICATE - Other instructions on reverse side

OCD-ARTESIA

1. Type of Well ☒ Oil Well ☐ Gas Well ☐ Other		8. Well Name and No. TURNER B 92
2. Name of Operator MERIT ENERGY COMPANY		9. API Well No. 30-015-26596-00-S1
3a. Address 13727 NOEL RD., STE 500 DALLAS, TX 752406		10. Field and Pool, or Exploratory GRAYBURG JACKSON
3b. Phone No. (include area code) Ph: 972.628.1630 Ext: 630 Fx: 972.960.1252		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 20 T17S R31E SESW 1305FSL 1350FWL		11. County or Parish, and State EDDY COUNTY, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
☒ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off
☐ Subsequent Report	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity
☐ Final Abandonment Notice	☐ Casing Repair	☐ New Construction	☐ Recomplete	☒ Other
	☐ Change Plans	☐ Plug and Abandon	☐ Temporarily Abandon	Workover Operations
	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

1. COMPLY W/COMPANY & GOVERNMENTAL SAFETY REGULATIONS.

2. RU PU. ND WH. NU BOP. TOH RODS PMP & TBG. TIH W/4-3/4" BIT ON 2-7/8" WS. CLEAN OUT TO 2400'. TOH W/BIT. TIH W/CIBP SET @ 2300'.

3. PERF SR 2032-2036', 1998-2002', 1942-1944', 1928-1932', 1916-1918', 1888'-1891', 1878-1880' & 1802-1804'(21' NET) W/4SPF.

4. TIH W/5-1/2" 17# STIMULATION PKR ON 2-7/8" WS SET PKR @ 1750'. ACIDIZE SR W/HCL PER CUDD. TIH W/3-1/2" MHMA W/PURGE VALVE, SN, 1 2-7/8" IPC JT, & 2-7/8" TBG W/TBG ANCHOR. SET SN BELOW BTM PERF. RUN GAS ANCHOR, PMP, SUCKER RODS W/T GRADE COUPLINGS.

14. I hereby certify that the foregoing is true and correct. Electronic Submission #24623 verified by the BLM Well Information System For MERIT ENERGY COMPANY, sent to the Carlsbad Committed to AFMSS for processing by ARMANDO LOPEZ on 10/29/2003 (04AL0041SE)	
Name (Printed/Typed) BEVERLY HATFIELD	Title AUTHORIZED SIGNATURE
Signature (Electronic Submission)	Date 10/29/2003

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By ALEXIS C SWOBODA	Title PETROLEUM ENGINEER	Date 10/30/2003
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office Carlsbad

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

Additional data for EC transaction #24623 that would not fit on the form

32. Additional remarks, continued

5. RETURN WELL TO PRODUCTION.