

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

SEP - 9 2008

OCD-ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

ISEB0826852549
NSEB0826852231

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company OXY USA	192463	Contact Kelton Beaird
Address 102 S Main Carlsbad, NM 88220		Telephone No. (O) 505-887-8337 C) 575-390-1903
Facility Name Righthand Canyon 34-1 sat.		Facility Type Active Well w/ Tank Battery

Surface Owner BLM	Mineral Owner	Lease No.
-------------------	---------------	-----------

30-015-27046

LOCATION OF RELEASE

Unit Letter	Section 34	Township 21S	Range 24E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
-------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced water /oil	Volume of Release 14 bbls	Volume Recovered 10bbls
Source of Release Pop-off on treater	Date and Hour of Occurrence 9-7-08	Date and Hour of Discovery 9-7-08/ 2:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos- BLM Mike Bratcher- NMOCD	
By Whom? Kelton Beaird Hes Oxy	Date and Hour See above	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Air Compressor failed causing all ESD's to shut except the one on the 34-1, causing water to overflow from the pop-off. Vac-truck was called to vacuum up all standing fluids.

Describe Area Affected and Cleanup Action Taken.*

Most contamination stayed inside the berms, approx 1 barrel of water released outside the berm. 10 bbls of water was reported released with 4 bbls of oil. All fluids were picked up. A clean up plan will be submitted for approval.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Kelton Beaird	Approved by District Supervisor: 	Remediation Actions to be completed and Final C-141 submitted with confirmation analyses/documentation on or before the Expiration Date.
Title: HES Specialist	Approval Date: 9-24-08	Expiration Date: 11-28-08
E-mail Address: kelton_beaird@oxy.com	Conditions of Approval:	Attached <input checked="" type="checkbox"/>
Date: 9-7-08	SEE ATTACHED STIPULATIONS	2RP-227

Attach Additional Sheets If Necessary

SEB0826852627

Notify OCD 48 hours prior to
obtaining samples where analyses
are to be presented to OCD