

January 8, 2008

Oil Conservation Division 1301 W. Grande Ave. Artesia, N.M. 88210

Attention: Bryan Arrant

Re: Dodd Federal Unit #536
Dodd Federal Unit #537
Dodd Federal Unit #540
Dodd Federal Unit #541
Dodd Federal Unit #543
Dodd Federal Unit #545
Dodd Federal Unit #545

Dodd Federal Unit #546

Dodd Federal Unit #547

Dodd Federal Unit #548

330' FSL & 990' FEL, Sec 10, T17S - R29E 330' FSL & 1650' FWL, Sec 10, T17S - R29E 2310' FSL & 2310' FWL, Sec 10, T17S - R29E 1650' FSL & 2310' FEL, Sec 10, T17S - R29E 1650' FSL & 990' FEL, Sec 10, T17S - R29E 2310' FSL & 990' FWL, Sec 11, T17S - R29E 1650' FSL & 2310' FEL, Sec 11, T17S - R29E 2310' FSL & 330' FEL, Sec 11, T17S - R29E 2310' FSL & 1690' FEL, Sec 15, T17S - R29E Eddy County, New Mexico Eddy County, New Mexico

Dear Bryan:

Marbob Energy has conducted a review to determine if an H2S contingency plan is required for the above referenced wells. We were able to conclude that any potential hazardous volume would be minimal. H2S concentrations of wells in this area from surface to TD are low enough; therefore we do not believe that an H2S Contingency Plan would be necessary.

Please advise us if you feel differently or need further information.

Sincerely,

Nancy Agnew

Manay agnew

Landman

/na