Form C-103 State of New Mexico JARTESIA Submit 3 Copies To Appropriate District Office Energy, Minerals and Natural Resources May 27, 2004 District I WELL API NO. 1625 N. French Dr., Hobbs, NM 87240 30-015-01670 District II OIL CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, NM 88210 5. Indicate Type of Lease 1220 South St. Francis Dr. District III FEE Santa Fe, NM 87505 🗐 STATE | x 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 6. State Oil & Gas Lease No. 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BẮĆK TO Å EMPIRE ABO UNIT 'G' DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS) 8. Well Number 1. Type of Well: Oil Well X Gas Well Other 2. Name of Operator 9. OGRID Number BP America Production Company 00778 10. Pool name or Wildcat 3. Address of Operator P.O. Box 1089 Eunice NM 88231 EMPIRE ABO 4. Well Location 1650 **1960.99** feet from the feet from the line and Township 17S Range 28E **NMPM** County EDDY 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3669' GR Pit or Below-grade Tank Application or Closure Pit type ______ Depth to Groundwater _____ Distance from nearest fresh water well ______ Distance from nearest surface water _____ Pit Liner Thickness: Below-Grade Tank: Volume____ _bbls; Construction Material . 12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. [**TEMPORARILY ABANDON CHANGE PLANS** PLUG AND **ABANDONMENT** CASING TEST AND PULL OR ALTER CASING MULTIPLE **CEMENT JOB** COMPLETION Notify OCD 24 hrs. prior OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Approval Granted providing work 1. MIRU PU. Pressure tbg to 500 psi. Have equipment ready on location to is complete by pump hot water. Kill casing as necessary. 2. Nipple up BOP. 3. Pull rods and tbg out of hole. Lay down rods. 4. TIH with CIBP on the and set @ 5750' (60' above top perf). 5. TIH and spot 25 sx of Class "C" cement on top of CIBP at 5750'. Plug set approx 5750' - 5400'. 6. Displace well with mud. Continued on page 2. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed of closed according to NMOCD guidelines _____, a general permit ____or an (attached) alternative OCD-approved plan ____ SIGNATURE 1 TITLE Area Operations Team Lead DATE E-mail address: barry.price@bp.com Type or print name Barry C. Price Telephone No. 575-394-1648

For State Use Only
APPROVED BY

Conditions of Approval, if any:

Form C-103 Empire Abo Unit G-27 30-015-01670 Continued from Page 1

- 7. Set a 25 sx balanced Class "C" cement plug across Glorieta formation, 3300' 3550', WOC and then tag. If top of plug OK (tagged above 3320) POOH to 920'.
- 8. Set a 65 sx balanced Class "C" cement plug at 920' to cover the surface csg shoe @ 868' and across top of Yates @ 375 and up to surface
- 9. If necessary after POOH w/ tbg, fill well bore with cement to 3' below GL.
- 10. RD PU and clean location.
- 11. Dig out WH and cut all casings and WH's to 3' below original GL or at base of cellar, whichever is deeper, and install regulation Dry Hole Marker.


Empire Abo Unit G-27 Empire Abo Field

. . . .

API No. 30-015-01670

1650' FSL & 1961' FEL Sec 32 - T17S - R28E Eddy County, New Mexico

Status 9-2-2008



Empire Abo Unit G-27 Empire Abo Field

. . . .

\

API No. 30-015-01670

1650' FSL & 1961' FEL Sec 32 - T17S - R28E Eddy County, New Mexico

Proposed P & A

