

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-32748
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator BTA Oil Producers		6. State Oil & Gas Lease No.
3. Address of Operator 104 S. Pecos; Midland, TX 79701		7. Lease Name or Unit Agreement Name:  Pardue "C", 8808 JV-P
4. Well Location  Unit Letter <u>M</u> : <u>430</u> feet from the <u>south</u> line and <u>990</u> feet from the <u>west</u> line Section <u>11</u> Township <u>23S</u> Range <u>28E</u> NMPM <u>Eddy</u> County		8. Well No. 4
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3008' GL 3021' KB		9. Pool name or Wildcat Loving; Brushy Canyon, East 40350

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data  
**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

BTA Oil Producers proposes to cement squeeze the Pardue Price Sand and recomplete to lower Brushy Canyon Sand as follows:

A small workover pit will be required.

1. MI & RU. POH w/rods & pmp.
2. NU BOP. POH w/tbg.
3. Run cmt ret for 5-1/2" csg on tbg. Set cmt ret @  $\pm 4650'$ .
4. Pmp 200 sx cmt, unstng from ret and rev out cmt.
5. POH w/tbg. PU mill and DC. RIH and drill out cmt ret and cmt. Circ hole clean.
6. Spot 200 gal acetic @ 5806'. POH w/tbg.
7. Perf 5722-5806'.
8. RIH w/tbg & pkr. Set pkr @  $\pm 5590'$ . Press test to 1000 psi.
9. Breakdown perfs and displace.
10. Swab back to evaluate.
11. Frac.
12. Flow back and swab.
13. Put on production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Pam Inskeep TITLE Regulatory Administrator DATE 11/12/2003

Type or print name Pam Inskeep Telephone No. (915) 682-3753

(This space for State use)  
APPROVED BY Jim W. Lewis TITLE District Supervisor DATE NOV 18 2003

Conditions of approval, if any: